		, -				
NO. OF COPIES MECHINIO			Form C	-103		
DISTRIBUTION	and a second contract from the second contract		_	Supersedex Old G-102 and G-103		
SANTA FE	NEW MEXICO OIL	ONSERVATION COMMISSION		vo 1-1-65		
FILE						
U.5.G.5,			1 ,	c Type of Le	150	
LAND OFFICE			State	V	Fee	
OPLRATOR			5. State O	1 & Gas Leas	e No.	
			B.	-963 8		
SUNDRY	NOTICES AND REPORTS	ON WELLS LUG BACK TO A DIFFERENT RESERVOIR R SUCH PHOPOSALS.)				
	FOR PERMIT -" WERM C-1011 FC	CUG BACK TO A DIFFERENT RESERVOIR. R SUCH LHOPOSALS.)		7//////	7777777	
1. OIL X WELL X WELL	•		7, Unit Agr	eement Name		
2. Figure of Operator	OTHER-			-		
TEXACO Inc.			6. 1'cam or	Lease Name	NCT-1	
3. Address of Operator				ico 'BN'	State	
	Nov. Monday 00240		9. Well No.	_		
P. O. Box 728 - Hobbs, I	New Mexico 88240			3		
1 2210 South 000				nd Pool, or W	'Ildoat	
UNIT LETTER L 2310 FEET FROM THE SOUTH LINE AND 990 FEET FROM				Moore Devonian		
THE West Line, Section 25 TOWNSHIP 11-S RANGE 32-E NMPM.						
THE West LINE, SECTION_	ZO TOWNSHIP	1-5 RANGE 32-L	NMPM.			
1777/77/77/77/77/77/77/	The Clause 181	ol., DE BT CO		777777		
	15. Elevation (Show who		12, County			
		33' (DF)	Lea	<u> </u>	7777777	
Check App	propriate Box To Indica	e Nature of Notice, Report of	or Other Data			
NOTICE OF INTE	ENTION TO:	SUBSEQ	UENT REPORT	OF:		
		(m)				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	X REMEDIAL WORK		ALTERING CAS	146	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.]	PLUG AND ABAR	OONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	_]			
		OTHER				
OTHER						
17. Describe Proposed or Completed Opera	tions (Clearly state all pertinent	details and give pertinent dates inc	Inding estimated do	to of starting		
work) SEE RULE 1703.	, , , , , , , , , , , , , , , , , , , ,	dotates, and give perturent dates, the	tacing estimated da	te of starting	uny proposeu	
1. Set CIBP at 10,500 fee	t and snot 351 (4 st	c) cement plug on top.				
i. Set office at 10,500 rec	e and spot so (4 s	cy comette plug on copi				
2. Load hole with mud (25	sx gel per 100 bbls	water).				
2. Load note with mad (Lo	3A 9C1 PC. 100 DD1.					
3. Run freepoint, cut 5-1	/2" casing and pull	•				
	• • • • • • • • • • • • • • • • • • • •	,				
4. Spot 100' (25 sx) ceme	nt plug across casi	ng stub, 50' above and	50' below.			
, , , , , , , , , , , , , , , , , , , ,						
5. Spot 100' (35 sx) ceme	nt plug across inte	rmediate casing shoe at	3522'.			
6. Spot 100' (35 sx) ceme	nt plug at 1700'.	•				
7. Spot 10' (4 sx) cement	plug at surface.		- 4			
•	. -	THE COMMISSION MUST BE	NOTIFIED 24			
8. Install marker and cle	an location.	COMMISSION MUST BE	CINNING OF			
		THE COMMISSION MUST BE HOURS FRIOR TO THE SE PLUS HIG OPERATIONS FOR APPROVED.	THE C-103			
		HO - NO COPERATIONS	/:-			
		TO BE APPROVED.				
18. I hereby certify that the information about	ve is true and complete to the be	st of my knowledge and belief.				
1/21/2-1	-					
SIGNED & WESTER	TITLE	Asst. Dist. Supt.	DATE	4-13-76		
Orig. Sign			HVI	Sign T	केल संक्ष्या <u>।</u>	
APPROVED BY			[A]	*** × :		
CONDITIONS OF APPROVAL, IF ANY	pv.				****	
SOURCE ON A SERVICE OF A SECTION AND SECTI						

CI CONTRACTOR CORNER

•