

|                        |  |  |
|------------------------|--|--|
| NO. OF COPIES RECEIVED |  |  |
| DISTRIBUTION           |  |  |
| SANTA FE               |  |  |
| FILE                   |  |  |
| U.S.G.S.               |  |  |
| LAND OFFICE            |  |  |
| OPERATOR               |  |  |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

|   |                              |
|---|------------------------------|
| 5a. Indicate Type of Lease                |                              |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.              |                              |
| E-8835                                    |                              |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|   |   |
|---|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>  | 7. Unit Agreement Name                            |
| 2. Name of Operator<br>TEXACO Inc.  | 8. Farm or Lease Name<br>New Mexico 'CQ' State    |
| 3. Address of Operator<br>P.O. Box 728, Hobbs, New Mexico 88240   | 9. Well No.<br>1                                  |
| 4. Location of Well<br>UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM<br>THE <u>West</u> LINE, SECTION <u>35</u> TOWNSHIP <u>10-S</u> RANGE <u>33-E</u> NMPM. | 10. Field and Pool, or Wildcat<br>Inbe Permo Penn |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br>4199' DF   | 12. County<br>Lea                                 |

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TEXACO Inc. proposes to revise plug and abandon procedure for subject well as follows:

1. Pump 100 sx cement down 2-3/8" tubing and out by pass @9575'. Fill annulus to 9000'. Leave cement in tubing from 7300' to 9600'.
2. Back off tubing @7200'.
3. Squeeze hole in casing @7300' w/50 sx Class 'C' cement.
4. Spot 20 sx cement plug across female tubing end @7200'. Load hole with mud.
5. Spot 25 sx cement plug from 3850' to 3950'. Load hole with mud.
6. Spot 10 sx plug at surface.'
7. Install 4" Dry Hole Marker extending 4' above ground level.
8. Clean location. Plug and abandon.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

|                                |  |                          |
|--------------------------------|--|--------------------------|
| SIGNED <u>[Signature]</u>      | TITLE <u>Assistant District Superintendent</u> | DATE <u>May 10, 1971</u> |
| APPROVED BY <u>[Signature]</u> | TITLE <u>SUPERVISOR DISTRICT 1</u>             | DATE <u>MAY 11 1971</u>  |
| CONDITIONS OF APPROVAL ANY:    |  |                          |

RECEIVED

MAY 1, 1971

OIL CONSERVATION COMM.  
HOBBBS, N. M.