

COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-7489	
7. Unit Agreement Name	
8. Farm or Lease Name	
Hisson State	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
N. Bagley Middle Penn	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Felmont Oil Corporation

3. Address of Operator
c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, NM 88240

4. Location of Well
UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM
THE West LINE, SECTION 15 TOWNSHIP 11 S RANGE 33 E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4273 KB

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug and abandon as follows:

Set bridge plug at 9150 & cap with 35' cement
Set bridge plug at 8450 & cap with 35' cement
Displace hole with 9.5# mud
Cut & pull 5 1/2" casing
Spot 100' plug @ top of Abo @ 7360 if above casing stub
Spot 100' plug across 5 1/2" casing stub
Spot 100' plug in & out of 8 5/8" casing shoe @ 3770
Cut & pull 8 5/8" casing
Spot 100' plug across 8 5/8" casing stub
Spot 100' plug across top Salt @ 1700 if above 8 5/8" casing stub
Spot 100' plug across 13 3/8" casing show @ 323
10 sack plug at surface with regulation marker
Location to be cleared and levelled.

100' PLUG REQUIRED AT TOP OF GLORIA

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. H. H. H. TITLE Agent DATE 3/4/76

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: