

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - P" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Hobbs Pipe Line Supply Company		8. Farm or Lease Name Humble A
3. ADDRESS OF OPERATOR P. O. Box 2010, Hobbs, New Mexico 88240		9. Well No. 1
4. Location of Well UNIT LETTER <u>1</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>27</u> TOWNSHIP <u>10-S</u> RANGE <u>33-E</u> NMPM.		10. Field and Pool, or Wildcat South Lane Penn
15. Elevation (Show whether DF, RT, CR, etc.) 4205' D.F.		12. County Lea

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

### 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. Propose to spot a 25 sx cement plug from 9709'-9715'.
2. Propose to spot a 25 sx cement plug at 4 1/2 casing stub at 7000'.
3. Propose to spot a 25 sx cement plug at top of Tubb at 6785'.
4. Propose to spot a 25 sx cement plug at 7-5/8 casing shoe at 3996'.
5. Propose to spot a 25 sx cement plug at 7-5/8 casing stub at 1000'.
6. Propose to spot a 25 sx cement plug at 10-3/4 casing shoe at 428'.
7. Propose to spot a 10 sx cement plug at surface with marker.
8. Hole will be loaded with mud-laden fluids.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Agent</u>	DATE <u>8/4/71</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>Geologist</u>	DATE <u>AUG 9 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

**RECEIVED**

**AUG 9 1971**

**OIL CONSERVATION COMM.  
HOBBS, N. M.**