

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG 3798	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection Well		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Coastal States Gas Producing Company		Flying "M" (SA) Unit Tr. 12
3. Address of Operator		9. Well No.
P. O. Box 235, Midland, Texas 79701		1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER L , 665 FEET FROM THE west LINE AND 1978 FEET FROM		Flying "M" (SA)
THE south LINE, SECTION 15 TOWNSHIP 9-S RANGE 33-E NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4368 GR		Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-12-74 - 4-16-74

1. Set Baker CIBP w/3 sx. cmt. @ 4928'. WOC 12. hrs.
2. Cut & pull 1206' 7-5/8" csg.
3. Set 50 sx. plug @ 1205'.
4. Set 60 sx. plug @ 400'.
5. Set 10 sx. plug @ surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *J.B. Shepherd* TITLE Dist. Prod. Manager DATE June 26, 1974

APPROVED BY *John W. Kunyan* TITLE General Manager DATE June 26, 1974

CONDITIONS OF APPROVAL, IF ANY:

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
OG 3798

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection Well	7. Unit Agreement Name Flying "M" (SA) Unit
2. Name of Operator Coastal States Gas Producing Company	8. Farm or Lease Name Flying "M" San Andres
3. Address of Operator P. O. Box 235, Midland, Texas 79701	9. Well No. 2-1
4. Location of Well UNIT LETTER L , 665 FEET FROM THE west LINE AND 1978 FEET FROM THE south LINE, SECTION 15 TOWNSHIP 9S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Flying "M" (SA)
15. Elevation (Show whether DF, RT, GR, etc.) 4368 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Give New Mexico Oil Conservation Commission, Hobbs office, 24 hours prior notice before setting plug.
2. Set CIBP at 4530'.
3. Spot a 35' cement plug above CIBP.
4. Determine free point; cut off and pull recoverable casing.
5. Mud up between all cement plugs with a 25 sx. salt gel/100 bbl. brine mixture.
6. Spot 100' cement plug in and out of casing stub.
7. Spot 100' cement plug from top of salt at 2050'.
8. Spot 100' cement plug in and out of surface casing bottomed at 350'.
9. Cap at surface with 10' cement plug.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE **District Production Manager** DATE **2-26-74**

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: