ERGY AND MINERALS DEPARTMENT	
OIL CONSERVATION DIVISION	Fora C-103
DISTRIBUTION P. O. BOX 2088	Revised 10-1-78
SANTA FE, NEW MEXICO 87501	Sa. Indicate Type of Laise
V.S.0.3.	State X Fee
LAND OFFICE	5. State Oil 6 Gas Lease No.
OPERATOR .	V-1366
SUNDRY NOTICES AND REPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FOR PROPOSALS TO DALL ON TO DELPEN ON PLUG BACK TO A DIFFERENT RESERVO	7. Unit Agreement Name
well X well ornen. Re-Entry	8. Farin or Lease Harre
Yates Petroleum Corporation	Carper-McAlester ACX St.
Idless of Operator	9. Well No. 1
207 South 4th St., Artesia, NM 88210	10. Field and Pool, c: wildcat
ocation of Well 1650	Eight Mile Draw Permo Penn
UNIT LETTER C 660 FEET FROM THE NOTTH LINE AND 1650	
	NUPM. (()))))))))))))))))))))))))))))))))))
TTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT	12. County
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Lea
Check Appropriate Box To Indicate Nature of Notice, Rep	port of Uther Data BSEQUENT REPORT OF:
NOTICE OF INTENTION TO:	BSEQUENT REPORT OF
PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
AFORM REMEDIAL WORK	S. PLUG ANT ABANDONMENT
LL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT	g for dropped tubing X
OTHER	
OTHER	
OTHER	ites, including estimated date of starting any proposed
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent da work) SEE AULE 1103.	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent da work) SEE AULE 1603. 22-85. Drilled out plugs and cleaned out hole to TD 11155'.	ing, collars and bit to run csg.
Describe Proponed or Completed Operations (Clearly state all pertinent details, and give pertinent da work) SEE AULE 1703. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub	ing, collars and bit to run csg. with 438' to bottom. Top fish @778
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent da work) SEE AULE 1703. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430	ing, collars and bit to run csg. with 438' to bottom. Top fish @778
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent da work) SEE AULE 1103. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430	ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent da work) see AULE 1103. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P	ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. OOH. RIH w/mill, could not get on e. POOH.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent da work) see AULE 1103. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P	ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. OOH. RIH w/mill, could not get on e. POOH.
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent da work) SEE AULE 1103. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P top of fish, tbg apparently laying against wall of hol 26-85. GIH w/mill and milled on tbg. POOH. GIH w/hook wall an 	ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. OOH. RIH w/mill, could not get on e. POOH. ad overshot, attempted to latch
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent da work) see AULE 1103. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P top of fish, tbg apparently laying against wall of hol 26-85. GIH w/mill and milled on tbg. POOH. GIH w/hook wall an onto tbg without success. 27-85. POOH. RIH w/concave mill and milled from 5801-5858'. P 	ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. 000H. RIH w/mill, could not get on e. POOH. ad overshot, attempted to latch 000H. RIH w/overshot, wall hook s-off mill and 5' cut-rite shoe.
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent da work) SEE AULE 1103. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P top of fish, tbg apparently laying against wall of hol 26-85. GIH w/mill and milled on tbg. POOH. GIH w/hook wall an onto tbg without success. 27-85. POOH. RIH w/concave mill and milled from 5801-5858'. P 	ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. 00H. RIH w/mill, could not get on e. POOH. ad overshot, attempted to latch 200H. RIH w/overshot, wall hook s-off mill and 5' cut-rite shoe.
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data work) ste auce 1703. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P top of fish, tbg apparently laying against wall of hol onto tbg without success. 27-85. POOH. RIH w/concave mill and milled from 5801-5858'. P and bent jt. Could not get fish. WBIH w/skirted dress 28-85. Rigged up wireline and fire string shot to blow fish comparison. 	ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. OOH. RIH w/mill, could not get on e. POOH. ad overshot, attempted to latch POOH. RIH w/overshot, wall hook s-off mill and 5' cut-rite shoe. but of wall. RIH w/knuckle jts,
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data work) ste auce 163. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P top of fish, tbg apparently laying against wall of hol onto tbg without success. 27-85. POOH. RIH w/concave mill and milled from 5801-5858'. P and bent jt. Could not get fish. WBIH w/skirted dress overshot and wall hook. Could not catch fish. 	<pre>ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. 000H. RIH w/mill, could not get on e. P00H. d overshot, attempted to latch 000H. RIH w/overshot, wall hook s-off mill and 5' cut-rite shoe. but of wall. RIH w/knuckle jts, rted mill and 1 it 7-7/8" wash</pre>
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent da work) see AULE 1103. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P top of fish, tbg apparently laying against wall of hol 26-85. GIH w/mill and milled on tbg. POOH. GIH w/hook wall an onto tbg without success. 27-85. POOH. RIH w/concave mill and milled from 5801-5858'. P and bent jt. Could not get fish. WBIH w/skirted dress 28-85. Rigged up wireline and fire string shot to blow fish covershot and wall hook. Could not catch fish. 29,30-85. POOH to run wash pipe with cut-rite lip. RIH w/skirted 	<pre>ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. 000H. RIH w/mill, could not get on e. P00H. ad overshot, attempted to latch 000H. RIH w/overshot, wall hook s-off mill and 5' cut-rite shoe. but of wall. RIH w/knuckle jts, rted mill and 1 jt 7-7/8" wash on skirt. RIH and milled to 5822'.</pre>
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent da work) ste aute 1703. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P top of fish, tbg apparently laying against wall of hol onto tbg without success. 27-85. POOH. RIH w/concave mill and milled from 5801-5858'. P and bent jt. Could not get fish. WBIH w/skirted dress overshot and wall hook. Could not catch fish. 29,30-85. POOH to run wash pipe with cut-rite lip. RIH w/skirte POOH. RIH w/knuckle jt and overshot w/41' spiral pipe 	ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. OOH. RIH w/mill, could not get on e. POOH. ad overshot, attempted to latch OOH. RIH w/overshot, wall hook s-off mill and 5' cut-rite shoe. but of wall. RIH w/knuckle jts, rted mill and 1 jt 7-7/8" wash on skirt. RIH and milled to 5822' guide, collars and 2 jts tbg.
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dawork) see AULE 1703. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P top of fish, tbg apparently laying against wall of hol onto tbg without success. 27-85. POOH. RIH w/concave mill and milled from 5801-5858'. P and bent jt. Could not get fish. WBIH w/skirted dress 28-85. Rigged up wireline and fire string shot to blow fish. 29,30-85. POOH to run wash pipe with cut-rite lip. RIH w/skirte POOH. RIH w/knuckle jt and overshot w/41' spiral pipe 31-9-2-85. Shut down for holiday. 	<pre>ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. 000H. RIH w/mill, could not get on e. POOH. ad overshot, attempted to latch 000H. RIH w/overshot, wall hook s-off mill and 5' cut-rite shoe. but of wall. RIH w/knuckle jts, rted mill and 1 jt 7-7/8" wash on skirt. RIH and milled to 5822' guide, collars and 2 jts tbg. 5802'. Mill locked up 7' past fish</pre>
 Describe Proposed or Completed Operations (Clearly state all pertinent details. and give pertinent data work) see AULE 1103. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P top of fish, tbg apparently laying against wall of hol 26-85. GIH w/mill and milled on tbg. POOH. GIH w/hook wall an onto tbg without success. 27-85. POOH. RIH w/concave mill and milled from 5801-5858'. P and bent jt. Could not get fish. WBIH w/skirted dress 28-85. Rigged up wireline and fire string shot to blow fish. 29,30-85. POOH to run wash pipe with cut-rite lip. RIH w/skirt pipe and milled 5719-5810'. POOH and dressed cut-rite POOH. RIH w/knuckle jt and overshot w/41' spiral pipe 31-9-2-85. Shut down for holiday. 	<pre>ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. 000H. RIH w/mill, could not get on e. POOH. ad overshot, attempted to latch 000H. RIH w/overshot, wall hook s-off mill and 5' cut-rite shoe. but of wall. RIH w/knuckle jts, rted mill and 1 jt 7-7/8" wash on skirt. RIH and milled to 5822' guide, collars and 2 jts tbg. 5802'. Mill locked up 7' past fish</pre>
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data work) sEE AULE 1103. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P top of fish, tbg apparently laying against wall of hol onto tbg without success. 27-85. POOH. RIH w/concave mill and milled from 5801-5858'. P and bent jt. Could not get fish. WBIH w/skirted dress overshot and wall hook. Could not catch fish. 29,30-85. POOH to run wash pipe with cut-rite lip. RIH w/skirte POOH. RIH w/knuckle jt and overshot w/41' spiral pipe and milled 5719-5810'. POOH and dressed cut-rite POOH. RIH w/knuckle jt and 41' spiral pipe guide. Washed to POOH. Greased side of pipe guide and RIH w/7-7/8" bit 	<pre>ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. 000H. RIH w/mill, could not get on e. P00H. d overshot, attempted to latch 000H. RIH w/overshot, wall hook s-off mill and 5' cut-rite shoe. out of wall. RIH w/knuckle jts, rted mill and 1 jt 7-7/8" wash on skirt. RIH and milled to 5822', guide, collars and 2 jts tbg. 5802'. Mill locked up 7' past fish and 6 collars to 5788'. Drilled to</pre>
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent da work) str auce 1763. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P top of fish, tbg apparently laying against wall of hol 66-85. GIH w/mill and milled on tbg. POOH. GIH w/hook wall an onto tbg without success. 27-85. POOH. RIH w/concave mill and milled from 5801-5858'. P and bent jt. Could not get fish. WBIH w/skirted dress 0 overshot and wall hook. Could not catch fish. 29,30-85. POOH to run wash pipe with cut-rite lip. RIH w/skirt pipe and milled 5719-5810'. POOH and dressed cut-rite POOH. RIH w/knuckle jt and overshot w/41' spiral pipe 31-9-2-85. Shut down for holiday. 3-85. RIH w/knuckle jt and 41' spiral pipe guide. Washed to POOH. Greased side of pipe guide and RIH w/7-7/8" bit 5803'. POOH. 	<pre>ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. 000H. RIH w/mill, could not get on e. P00H. ad overshot, attempted to latch 000H. RIH w/overshot, wall hook s-off mill and 5' cut-rite shoe. but of wall. RIH w/knuckle jts, rted mill and 1 jt 7-7/8" wash on skirt. RIH and milled to 5822' guide, collars and 2 jts tbg. 5802'. Mill locked up 7' past fish and 6 collars to 5788'. Drilled to set.</pre>
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data work) sEE AULE 1763. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P top of fish, tbg apparently laying against wall of hol onto tbg without success. 27-85. POOH. RIH w/concave mill and milled from 5801-5858'. P and bent jt. Could not get fish. WBIH w/skirted dress overshot and wall hook. Could not catch fish. 29,30-85. POOH to run wash pipe with cut-rite lip. RIH w/skirte POOH. RIH w/knuckle jt and overshot w/41' spiral pipe and milled 5719-5810'. POOH and dressed cut-rite POOH. RIH w/knuckle jt and overshot w/41' spiral pipe .31-9-2-85. RIH w/knuckle jt and 41' spiral pipe guide. Washed to POOH. Greased side of pipe guide and RIH w/7-7/8" bit 	<pre>ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. 000H. RIH w/mill, could not get on e. P00H. nd overshot, attempted to latch 000H. RIH w/overshot, wall hook s-off mill and 5' cut-rite shoe. out of wall. RIH w/knuckle jts, rted mill and 1 jt 7-7/8" wash on skirt. RIH and milled to 5822'. guide, collars and 2 jts tbg. 5802'. Mill locked up 7' past fish and 6 collars to 5788'. Drilled to </pre>
 Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dawork) set duce i ros. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P top of fish, tbg apparently laying against wall of hol onto tbg without success. 27-85. POOH. RIH w/concave mill and milled from 5801-5858'. P and bent jt. Could not get fish. WBIH w/skirted dress 28-85. Rigged up wireline and fire string shot to blow fish overshot and wall hook. Could not catch fish. 29,30-85. POOH to run wash pipe with cut-rite lip. RIH w/skirte pipe and milled 5719-5810'. POOH and dressed cut-rite POOH. RIH w/knuckle jt and overshot w/41' spiral pipe 31-9-2-85. Shut down for holiday. 3-85. RIH w/knuckle jt and 41' spiral pipe guide. Washed to POOH. Greased side of pipe guide and RIH w/7-7/8" bit 5803'. POOH. 	<pre>ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. 000H. RIH w/mill, could not get on e. P00H. ad overshot, attempted to latch 000H. RIH w/overshot, wall hook s-off mill and 5' cut-rite shoe. but of wall. RIH w/knuckle jts, rted mill and 1 jt 7-7/8" wash on skirt. RIH and milled to 5822'. guide, collars and 2 jts tbg. 5802'. Mill locked up 7' past fish and 6 collars to 5788'. Drilled to net. visor</pre>
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent da work) ste aut e 1103. 22-85. Drilled out plugs and cleaned out hole to TD 11155'. 23-85. Conditioned hole f/4 hrs to run csg. Start TOOH w/tub Pulled 778' of tbg - pin jumped collar and dropped tbg 24-85. WIH w/overshot. Latched onto tbg at 778'. POOH w/430 Top of fish now 5801'. 25-85. GIH w/overshot to 5801'. Could not latch onto tbg. P top of fish, tbg apparently laying against wall of hol and to tbg without success. 27-85. POOH. RIH w/concave mill and milled from 5801-5858'. P and bent jt. Could not get fish. WBIH w/skirted dress overshot and wall hook. Could not catch fish. 29,30-85. POOH to run wash pipe with cut-rite lip. RIH w/skirt pipe and milled 5719-5810'. POOH and dressed cut-rite POOH. RIH w/knuckle jt and overshot w/41' spiral pipe 31-9-2-85. Shut down for holiday. 3-85. RIH w/knuckle jt and 41' spiral pipe guide. Washed to POOH. Greased side of pipe guide and RIH w/7-7/8" bit 5803'. POOH. 	<pre>ing, collars and bit to run csg. with 438' to bottom. Top fish @778 3' tbg, last 3 jts corkscrewed. 000H. RIH w/mill, could not get on e. P00H. ad overshot, attempted to latch 000H. RIH w/overshot, wall hook s-off mill and 5' cut-rite shoe. but of wall. RIH w/knuckle jts, rted mill and 1 jt 7-7/8" wash on skirt. RIH and milled to 5822' guide, collars and 2 jts tbg. 5802'. Mill locked up 7' past fish and 6 collars to 5788'. Drilled to set.</pre>