

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SEP 10 1969

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
6. Field or Lease Name New Mexico "A" State
9. Well No. 1
10. Field and Pool, or Wildcat Inbo-Wolfcamp
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Sun Oil Company
3. Address of Operator P. O. Box 2792, Odessa, Texas 79760
4. Location of Well UNIT LETTER <u>0</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1830</u> FEET FROM THE <u>East</u> LINE, SECTION <u>7</u> TOWNSHIP <u>11 S</u> RANGE <u>34 E</u> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 4210 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Run cast iron bridge plug and set @ 9300', dump 2 sks common cement on top of bridge plug. Pull and recover approximately 5000', 4 1/2" casing. Spot 25 sk cement plug across 4 1/2" casing stub. Spot 25 sk cement plug across 8 5/8" casing seated at 4010'. Spot 10 sk cement plug at surface and install permanent marker.

Note: Plugging procedure approved by Mr. Joe Ramey w/ NMOCC. If more than 5000' of 4 1/2" casing is recovered a 25 sk plug will be spotted across the Glerietta at approx. 5600'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John M. Sweeney TITLE Ass't Dist. Superintendent DATE 9-4-69
APPROVED BY [Signature] TITLE SUPERVISOR DISTRICT DATE
CONDITIONS OF APPROVAL, IF ANY: