Submit 3 Copies to Appropriate District Office

State of New Mexico

Form C-103 Revised 1-1-89

DISTRICT P.O. Box 1980, Hobbs, NM 88240

P.O. Drawer DD, Artesia, NM 88210

DISTRICTIII A ---- NB4 97410

Minerals and Natural Resources Department Ener

OIL	CONS	SERVA	ATION	DIV	ISIO	V
-----	------	-------	-------	-----	------	---

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL AP	I NO.	
5. Indicat	e Type of Lease	FEE

5.	State Oil & Gas Lease No.
	LG-4129

1000 Rio Brazos Rd., Aziec, Nivi 6/410	LG-4129
SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
I. Type of Well: OIL GAS WELL X WELL OTHER	State "CZ"
Name of Operator  Tipton & Denton Duright A Tipton  Address of Operator	8. Well No. 1
c/o Oil Reports & Gas Services, Box 763, Hobbs, N	9. Pool name or Wildcat M Jenkins - SA
Well Location Unit Letter $\underline{L}:\underline{1980}$ Feet From The $\underline{South}$ Line and $\underline{660}$	
Section 27 Township 9-S Range 35-E	NMPM Lea County
10. Elevation (Show whether Dr., RRB, R1, GR, EC.)	<i>''</i> ///////////////////////////////////

<u> </u>	71 - 1- 4	Dou to Indi	ionto N	Nature of Notice, Report, or	Othe	r Data	
		-	icale i				
NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF				
PERFORM REMEDIAL WORK		PLUG AND ABANDON	XX	REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPNS.		PLUG AND ABANDONMENT	
PULL OR ALTER CASING				CASING TEST AND CEMENT JO	в		
OTHER:				OTHER:			<u></u>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4136 KB

- 1. Set 4-1/2" CIBP @ 4950' & cap w/ 35' cmt.
- 2. Circ. 4-1/2" csg. w/ mud laden fluid.
- 3. Cut 4-1/2" csg. @ 4166' & lay dwn. 4. Spot 150' cmt plug from 4216'- 4066'. (50' in 4-1/2" stub to 50' above 8-5/8" csg. shoe).
- 5. Spot 100' plug @ top of salt from 1800'- 1700'.
- 6. Spot 10 sx surface plug.
- 7. Install Dry Hole marker & clean location.

	formation above is true and complete to the best of	Consultant	4-2-92
SIGNATURE		mr.E	393-7320
TYPE OR PRINT NAME	Paul Bliss		TELEPHONE NO.
(Thus space for State Use)	Orig. Signed by. Paul Kautz Geologist		Vod 03.
APPROVED BY		TITLE	DATE