Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION	WELL API NO.
2040 Pacheco St.	30 025 20631
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	sIndicate Type of Lease
	STATE FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	sState Oil & Gas Lease No.
	FLYING M SA UNIT
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	e emiliare de la companya del companya de la companya del companya de la companya del la companya de la company
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	rLease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)	FLYING M SA UNIT
Type of Well: OIL GAS WELL WELL OTHER WIW	
2Name of Operator	sWell No.
SOUTHWEST ROYALTIES, INC.	15-2 152
sAddress of Operator PO BOX 11390 MIDLAND, TX 79702	∍Pool name or Wildcat FLYING M SA
«Well Location	
Unit Letter N : 660 Feet From The SCUTH Line and 1985	Feet From The WEST Line
21 Section 9 Township 33 Range	NMPM LEA County
₁₀Elevation (Show whether DF, RKB, RT, GR, etc.) 4352.4	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
· · · · · · · · · · · · · · · · · · ·	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING C	
	<u> </u>
PULL OR ALTER CASING CASING TEST AND CEM	ENT JOB
	ENT JOB
OTHER: OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimates)	
OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including eswork) SEE RULE 1103. 10/15 - 10/17/97 RUPU, NDWH, NU BOP, RELEASE PKR, & POH. RIH W/3-7/8" BIT & TOWNS AND	stimated date of starting any proposed
OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including eswork) SEE RULE 1103. 10/15 - 10/17/97 RUPU, NDWH, NU BOP, RELEASE PKR, & POH. RIH W/3-7/8" BIT & BY PREVIOUS OPERATOR) PUSHED AD-1 PKR TO 4492' & POH W/BIT.	stimated date of starting any proposed TAG UP @ 4480' (AD-1 PKR LEFT IN HOLE
OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including eswork) SEE RULE 1103. 10/15 - 10/17/97 RUPU, NDWH, NU BOP, RELEASE PKR, & POH. RIH W/3-7/8" BIT & TOWNS AND	stimated date of starting any proposed TAG UP @ 4480' (AD-1 PKR LEFT IN HOLE
OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including es work) SEE RULE 1103. 10/15 - 10/17/97 RUPU, NDWH, NU BOP, RELEASE PKR, & POH. RIH W/3-7/8" BIT & BY PREVIOUS OPERATOR) PUSHED AD-1 PKR TO 4492' & POH W/BIT. 10/18 - 10/22/97 SET RBP @ 4430' & TESTED. LOCATED BAD CSG @ 1200' TO 1360	ratimated date of starting any proposed TAG UP @ 4480' (AD-1 PKR LEFT IN HOLE 'F.S. RAN FREE POINT ON 4-1/2" CSG.
OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including eswork) SEE RULE 1103. 10/15 - 10/17/97 RUPU, NDWH, NU BOP, RELEASE PKR, & POH. RIH W/3-7/8" BIT & BY PREVIOUS OPERATOR) PUSHED AD-1 PKR TO 4492' & POH W/BIT. 10/18 - 10/22/97 SET RBP @ 4430' & TESTED. LOCATED BAD CSG @ 1200' TO 1360 SHOWED STUCK @ 377' F.S. 10/26/97 RIH W/3-1/2" - 9.3# CSG TO 4360'UNABLE TO GET ANY DEEPER.	ratimated date of starting any proposed TAG UP @ 4480' (AD-1 PKR LEFT IN HOLE 'F.S. RAN FREE POINT ON 4-1/2" CSG.
OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including eswork) SEE RULE 1103. 10/15 - 10/17/97 RUPU, NDWH, NU BOP, RELEASE PKR, & POH. RIH W/3-7/8" BIT & BY PREVIOUS OPERATOR) PUSHED AD-1 PKR TO 4492' & POH W/BIT. 10/18 - 10/22/97 SET RBP @ 4430' & TESTED. LOCATED BAD CSG @ 1200' TO 1360 SHOWED STUCK @ 377' F.S. 10/26/97 RIH W/3-1/2" - 9.3# CSG TO 4360'UNABLE TO GET ANY DEEPER. W/220 SX CLASS "C", .3% CFR-3 + 100 SXS PPCEMENT CIRC TO SURFACE.	ratimated date of starting any proposed TAG UP @ 4480' (AD-1 PKR LEFT IN HOLE 'F.S. RAN FREE POINT ON 4-1/2" CSG. CEMENTED LINER
OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including eswork) SEE RULE 1103. 10/15 - 10/17/97 RUPU, NDWH, NU BOP, RELEASE PKR, & POH. RIH W/3-7/8" BIT & BY PREVIOUS OPERATOR) PUSHED AD-1 PKR TO 4492' & POH W/BIT. 10/18 - 10/22/97 SET RBP @ 4430' & TESTED. LOCATED BAD CSG @ 1200' TO 1360 SHOWED STUCK @ 377' F.S. 10/26/97 RIH W/3-1/2" - 9.3# CSG TO 4360'UNABLE TO GET ANY DEEPER. W/220 SX CLASS "C", .3% CFR-3 + 100 SXS PPCEMENT CIRC TO SURFACE. 10/28 - 10/30/97 DRILL OUT CEMENT & SHOE.	stimated date of starting any proposed TAG UP @ 4480' (AD-1 PKR LEFT IN HOLE 'F.S. RAN FREE POINT ON 4-1/2" CSG. CEMENTED LINER /16" PKR + 2-1/16" TBG SET PKR @ 4332'.
OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including eswork) SEE RULE 1103. 10/15 - 10/17/97 RUPU, NDWH, NU BOP, RELEASE PKR, & POH. RIH W/3-7/8" BIT & BY PREVIOUS OPERATOR) PUSHED AD-1 PKR TO 4492' & POH W/BIT. 10/18 - 10/22/97 SET RBP @ 4430' & TESTED. LOCATED BAD CSG @ 1200' TO 1360 SHOWED STUCK @ 377' F.S. 10/26/97 RIH W/3-1/2" - 9.3# CSG TO 4360'UNABLE TO GET ANY DEEPER. W/220 SX CLASS "C", .3% CFR-3 + 100 SXS PPCEMENT CIRC TO SURFACE. 10/28 - 10/30/97 DRILL OUT CEMENT & SHOE. 10/31/97 ACIDIZED SA ZONE W/2500 GALS OF 15% ACID, RIH W/3-1/2" X 2-1. 11/3/97 RAN CIT @ 350#HELD FOR 30 MINCHART ATTACHED (NO WITN	stimated date of starting any proposed TAG UP @ 4480' (AD-1 PKR LEFT IN HOLE 'F.S. RAN FREE POINT ON 4-1/2" CSG. CEMENTED LINER /16" PKR + 2-1/16" TBG SET PKR @ 4332'.
OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including eswork) SEE RULE 1103. 10/15 - 10/17/97 RUPU, NDWH, NU BOP, RELEASE PKR, & POH. RIH W/3-7/8" BIT & BY PREVIOUS OPERATOR) PUSHED AD-1 PKR TO 4492' & POH W/BIT. 10/18 - 10/22/97 SET RBP @ 4430' & TESTED. LOCATED BAD CSG @ 1200' TO 1360 SHOWED STUCK @ 377' F.S. 10/26/97 RIH W/3-1/2" - 9.3# CSG TO 4360'UNABLE TO GET ANY DEEPER. W/220 SX CLASS "C", .3% CFR-3 + 100 SXS PPCEMENT CIRC TO SURFACE. 10/28 - 10/30/97 DRILL OUT CEMENT & SHOE. 10/31/97 ACIDIZED SA ZONE W/2500 GALS OF 15% ACID, RIH W/3-1/2" X 2-1. 11/3/97 RAN CIT @ 350#HELD FOR 30 MINCHART ATTACHED (NO WITN	stimated date of starting any proposed TAG UP @ 4480' (AD-1 PKR LEFT IN HOLE 'F.S. RAN FREE POINT ON 4-1/2" CSG. CEMENTED LINER /16" PKR + 2-1/16" TBG SET PKR @ 4332'.
OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including eswork) SEE RULE 1103. 10/15 - 10/17/97 RUPU, NDWH, NU BOP, RELEASE PKR, & POH. RIH W/3-7/8" BIT & BY PREVIOUS OPERATOR) PUSHED AD-1 PKR TO 4492' & POH W/BIT. 10/18 - 10/22/97 SET RBP @ 4430' & TESTED. LOCATED BAD CSG @ 1200' TO 1360 SHOWED STUCK @ 377' F.S. 10/26/97 RIH W/3-1/2" - 9.3# CSG TO 4360'UNABLE TO GET ANY DEEPER. W/220 SX CLASS "C", .3% CFR-3 + 100 SXS PPCEMENT CIRC TO SURFACE. 10/28 - 10/30/97 DRILL OUT CEMENT & SHOE. 10/31/97 ACIDIZED SA ZONE W/2500 GALS OF 15% ACID, RIH W/3-1/2" X 2-1. 11/3/97 RAN CIT @ 350#HELD FOR 30 MINCHART ATTACHED (NO WITN	stimated date of starting any proposed TAG UP @ 4480' (AD-1 PKR LEFT IN HOLE 'F.S. RAN FREE POINT ON 4-1/2" CSG. CEMENTED LINER /16" PKR + 2-1/16" TBG SET PKR @ 4332'.
OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including exwork) SEE RULE 1103. 10/15 - 10/17/97 RUPU, NDWH, NU BOP, RELEASE PKR, & POH. RIH W/3-7/8" BIT & BY PREVIOUS OPERATOR) PUSHED AD-1 PKR TO 4492' & POH W/BIT. 10/18 - 10/22/97 SET RBP @ 4430' & TESTED. LOCATED BAD CSG @ 1200' TO 1360 SHOWED STUCK @ 377' F.S. 10/26/97 RIH W/3-1/2" - 9.3# CSG TO 4360'UNABLE TO GET ANY DEEPER. W/220 SX CLASS "C", .3% CFR-3 + 100 SXS PPCEMENT CIRC TO SURFACE. 10/28 - 10/30/97 DRILL OUT CEMENT & SHOE. 10/31/97 ACIDIZED SA ZONE W/2500 GALS OF 15% ACID, RIH W/3-1/2" X 2-1/2 (1/3)/97 RAN CIT @ 350#HELD FOR 30 MINCHART ATTACHED (NO WITN @ 60# INJECTION PRESSURE.	TAG UP @ 4480' (AD-1 PKR LEFT IN HOLE 'F.S. RAN FREE POINT ON 4-1/2" CSG. CEMENTED LINER /16" PKR + 2-1/16" TBG SET PKR @ 4332'. NESS)RETURN TO INJECTION 1000 BPD
OTHER: OTHER: DOTHER: DOTHER: DOTHER: DOTHER: DOTHER: DOTHE	ratimated date of starting any proposed TAG UP @ 4480' (AD-1 PKR LEFT IN HOLE 'F.S. RAN FREE POINT ON 4-1/2" CSG. CEMENTED LINER /16" PKR + 2-1/16" TBG SET PKR @ 4332'. NESS)RETURN TO INJECTION 1000 BPD
OTHER: OTHER: OTHER:	TAG UP @ 4480' (AD-1 PKR LEFT IN HOLE 'F.S. RAN FREE POINT ON 4-1/2" CSG. CEMENTED LINER /16" PKR + 2-1/16" TBG SET PKR @ 4332'. NESS)RETURN TO INJECTION 1000 BPD OR DATE 11-05-97
OTHER: OTHER: OTHER:	TAG UP @ 4480' (AD-1 PKR LEFT IN HOLE 'F.S. RAN FREE POINT ON 4-1/2" CSG. CEMENTED LINER /16" PKR + 2-1/16" TBG SET PKR @ 4332'. NESS)RETURN TO INJECTION 1000 BPD OR DATE 11-05-97

CONDITIONS OF APPROVAL, IF ANY: