Submit 3 Copies to Appropriate District Office

I hereby certify that the

(This space for State Use)

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY

TYPE OR PRINT NAME BEVERLY HATPIELD

SIGNATURE

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DATE 3

DATE

TELEPHONE NO. 915 686-9927

1996

OIL CONSERVATION DIVISION DISTRICT I P.O. Box 1980, Hobbs, NM 88240 WELL API NO. 2040 Pacheco St. Santa Fe, NM 87505 30 025 20642 DISTRICT II
P.O. Drawer DD, Artesia, NM 88210 Indicate Type of Lease STATE FEE DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 State Oil & Gas Lease No. NM 058102 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) FLYING M (SA) UNIT 1Type of Well: GAS WELL WELL OTHER CONVERT TO WIW «Well No. Name of Operator SOUTHWEST ROYALTIES, INC. ATTN: BEVERLY HATFIELD (7)**س**به 1 Address of Operator Pool name or Wildcat P. O. BOX 11390; MIDLAND, TX 79702 FLYING M (SA) 4Well Location SOUTH 2307 Feet From The 2310 **EAST** Unit Letter \_ Feet From The \_ : \_ Line and Line 98 21 Section 33 E LEA NMPM Township Range County 10 Elevation (Show whether DF, RKB, RT, GR, etc.) 4356 GL Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON PERFORM REMEDIAL WORK REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ANBANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB X OTHER: CONVERT TO WATER INJECTION OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. POH W/RODS & PMP; ND WH; RELEASE TAC & POH W/TBG. 2. RIH W/BIT & CLEAN OUT WELL TO PBTD; CIRC CLEAN & POH W/BIT. 3. RIH W/4-1/2" X 2-3/8" LOK-SET PKR AND 2-3/8" IPC TUBING. SET PKR @ ± 4390' (PERFS: 4476-4515'). 4. LOAD ANNULUS W/PACKER FLUID & TEST CSG TO 500# WITH CHART RECORDER. 5. ACIDIZE SAN ANDRES W/3000 GALS 20% NEFE ACID. 6. LAY INJECTION LINE & PUT WELL ON INJECTION.

complete to the best of my knowledge and belief.

43

TITLE

TITLE COMPLIANCE SPECIALIST