

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30025-20838
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NM 058102
7. Lease Name or Unit Agreement Name Flying "M" (SA) Unit Tr. 4
8. Well No. 3
9. Pool name or Wildcat Flying "M" (SA)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Coastal Oil & Gas Corporation
3. Address of Operator P.O. Box 235, Midland, Texas 79702
4. Well Location Unit Letter <u>H</u> : <u>796</u> Feet From The <u>East</u> Line and <u>2116</u> Feet From The <u>North</u> Line Section <u>17</u> Township <u>9-S</u> Range <u>33-E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4374' GL

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Coastal Oil & Gas Corporation
3. Address of Operator P.O. Box 235, Midland, Texas 79702
4. Well Location Unit Letter <u>H</u> : <u>796</u> Feet From The <u>East</u> Line and <u>2116</u> Feet From The <u>North</u> Line Section <u>17</u> Township <u>9-S</u> Range <u>33-E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4374' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NOTE: SA perfs 4436'-45'

11-19-92 MIRU. GIH with bit, could not get past 3452'. POOH. GIH with open ended  
thru tubing to 4130'. Circ hole with gelled brine (9.8 PPG). Spotted 25 sack  
11-23-92 plug, POOH 20 stands, SDFN. GIH, tag cmt plug at 3812' (Plug #1 4130'-3812').  
POOH to 3502', spotted 25 sack plug 3502'-3213'. POOH to 1915', spotted 25  
sack plug 1915'-1626'. POOH. RU WL, perf squeeze holes at 440', RD WL.  
GIH with retainer, set at 360', squeezed below retainer with 50 sacks. Good  
circ to surface behind 8-5/8", did not circ cmt. Spotted 10 sack surface plug.  
Well P&A'd 11-24-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bobby L. Smith TITLE Sr. Petroleum Engineer DATE 11-24-92  
TYPE OR PRINT NAME Bobby L. Smith TELEPHONE NO. 915 682-7925

(This space for State Use)

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE JAN - 6 1993  
CONDITIONS OF APPROVAL, IF ANY: