NO. OF COPIES RECEIVED		Form C-103 Supersedes Old
DISTRIBUTION		C-102 and C-103 Effective 1-1-65
SANTA FE	TA FE NEW MEXICO OIL CONSERVATION COMMISSION	
FILE		Sa. Indicate Type of Lease
U.S.G.S.	.s.g.s.	
LAND OFFICE		State X Fee  5. State Oil & Gas Lease No.
OPERATOR		- Gus Lease
SUND (DO NOT USE THIS FORM FOR P USE "APPLIC	7. Unit Agreement Name	
I. OIL X GAS	- Ont Agreement Name	
2. Name of Operator	8. Form or Lease Name	
1	New Mexico "C" State	
Sun Oil Company  3. Address of Operator	9. Well No.	
P. O. Box 1861 - Mid	2	
	10. Field and Pool, or Wildcat	
4. Location of Well	660 North 660	Inbe Permo Penn
UNIT LETTER	660 FEET FROM THE North LINE AND 660 FEET FROM	
THE West LINE, SEC	TION 7 TOWNSHIP 11-S RANGE 34-E NMPM.	
	15. Elevation (Show whether DF, RT, GR, etc.) 4212 DF	12. County Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JQB OTHER	ALTERING CASING PLUG AND ABANDONMENT X
OTHER		
		in a day of coaring any proposed
	i Operations (Clearly state all pertinent details, and give pertinent dates, including	
(1) 7-1-72 Halliburton sptd. 4 sx. sd. 9769-9725 & 50 sx. Cmt. plug 9725-9175.		
(2) 7-2-72 Bonanza MIRU. Load hole w/9# mud.		
(3) $7-5-72$ Sht. $4\frac{1}{2}$ " csg. @ 5630 & pull.		
(4) 7-7-72 Sptd. 100 sx. cmt. plug 5630-5200 & 75 sx. cmt. plug 4000-3738.		
(5) 7-8-72 Sht. 8-5/8" csg. @ 1017 & pull. Sptd. 70 sx. cmt. plug 1067-967 & 75 sx. cmt. plug 450-335. 10 sx. plug to surf.		
(6) 7-9-72 Set P &	A marker -COMPLETE-	· ·

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Rayles Say TITLE Proration Clerk DATE 8-4-72

APPROVED STATE CONDITIONS OF APPROVAL, IF ANY: