

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
06-4558

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator SIGNAL OIL & GAS COMPANY	8. Farm or Lease Name STATE "AP" COM
3. Address of Operator 125 Central Building, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>I</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>17</u> TOWNSHIP <u>10-S</u> RANGE <u>34-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Vada, Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4231 K.B.	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Place Cast Iron Bridge Plug at 9900'.
2. Cut 5-1/2" production casing at approx. 4100'
3. Pull 5-1/2" casing.
4. Place 25 sk. cement plug at 5-1/2" csg. stub.
5. Place 25 sk cement plug at shoe of 8-5/8 intermediate casing.
6. Place 10 sk. cement plug at surface & erect required monument.

We would like to commence this work November 13, 1970.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D.J. Delany TITLE Division Production Engineer DATE 11/9/70

APPROVED BY John W. Runyan TITLE Manager DATE NOV 11 1970

CONDITIONS OF APPROVAL, IF ANY: