

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

JUL 27 4 12 PM '65

5a. Indicate Type of Lease	State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> WELL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> OTHER- <b>Dry</b>	7. Unit Agreement Name
2. Name of Operator <b>Texas Pacific Oil Company</b>	8. Farm or Lease Name <b>T.P. State</b>
3. Address of Operator <b>P. O. Box 1069, Hobbs, New Mexico</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>A</b> , <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>6</b> TOWNSHIP <b>10-S</b> RANGE <b>37-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We plugged and abandoned this well as follows.

- Moved in casing pulling unit.
- Ran 159 Jts. 2-3/8" tubing. Set at 4927'.
- Set 10 sks. cmt. plug from 4827-4927' (across perms.).
- Pulled tubing.
- Shot pipe at 650'. Recovered 644' of 4-1/2" casing.
- Spotted 25 sks. cmt. plug at 685'.
- Spotted 25 sks. cmt. plug at 450'.
- Set 10 sks. cmt. plug at surface and set marker.
- Plugged and Abandoned 6-23-65. Location has been cleaned.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. Deato TITLE Area Engineer DATE July 26, 1965

APPROVED BY [Signature] TITLE [Signature] DATE NOV 10 1965

CONDITIONS OF APPROVAL, IF ANY: