

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

MAY 29 12 46 AM '69

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>E-1110</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>New Mexico "AF" State</b>
9. Well No. <b>3</b>
10. Field and Pool, or Wildcat <b>Mescalero San Andres</b>
12. County <b>Lea</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator <b>Morris R. Antweil</b>
3. Address of Operator <b>Box 2010, Hobbs, New Mexico 88240</b>
4. Location of Well UNIT LETTER <b>J</b> <b>2160</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM <b>East</b> THE <b>27</b> LINE, SECTION <b>10-S</b> TOWNSHIP <b>32-E</b> RANGE <b>32-E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>4336' DF</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Well was plugged and abandoned as follows:**

1. Spotted 25 sx cement plug across perfs 4050'-4138'.
2. Hole was loaded with mud-laden fluid.
3. Cut and Pulled 900' 4-1/2" casing.
4. Spotted 25 sx cement plug across 4-1/2" casing stub @ 900'.
5. Spotted 25 sx cement plug across 8-5/8" casing shoe @ 404'.
6. Spotted 10 sx surface plug with marker.

**Plugged and abandoned 6 May 69.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R M Williams TITLE Agent DATE May 28, 1969

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: