

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDARY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR OPERATIONS TO BE PERFORMED IN A NON-PRODUCING RESERVOIR.
USE THIS FORM FOR OPERATIONS TO BE PERFORMED IN A PRODUCING RESERVOIR.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
Sun Oil Company

Address of Operator
P. O. Box 1861 Midland, Texas 79702

Location of Well
UNIT LETTER **C** **660** FEET FROM THE **North** LINE AND **1650** FEET FROM
THE **West** LINE, SECTION **26** TOWNSHIP **10S** RANGE **32E** RANGE

13. Elevation (Sea level or BOP, KT, GR, etc.)
4322 DF

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Name of Lease Name
New Mexico "E" State

9. Well No.
3

10. Field and Pool, or Wildcat
Mescalero San Andres

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER **Clean up well and Acidize** ☒

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU. Install BOP.
- 2) Pull rods and pump. Lower tbg. and tag btm. POH.
- 3) RIH w/tbg and RDG pkr w/1 jt. of tailpipe. Load annulus with lease crude. Use HOWCO to spot 100 gal 15% PAD acid 4171-4025. Pull up and set pkr. appx. 3990'. Pressure backside to 500 psi.
- 4) Displace spotted acid into formation w/10 bbls lse crude. Acidize perfs 4124-71 w/2500 gal 15% PAD acid, dropping 1 RCNBS per every 100 gals of acid (Total of 25 balls). Acidize at 3-BPM. Flush w/lease crude. Flush w/lease crude. All acid and lease crude to contain frictic reducer.
- 5) Pull tbg and RDG. RIH w/tbg. rods and pump as before.
- 6) RR. Put on production and test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Don Harry* TITLE Office Assistant DATE 4-25-78

APPROVED BY _____ TITLE _____ DATE _____

ADDITIONS OF APPROVAL, IF ANY: