

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>Sun Oil Company</b>		8. Farm or Lease Name <b>New Mexico "E" St.</b>
3. Address of Operator <b>P. O. Box 1861, Midland, Texas 79701</b>		9. Well No. <b>3</b>
4. Location of Well UNIT LETTER <b>C</b> , <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>1650</b> FEET FROM THE <b>West</b> LINE, SECTION <b>26</b> TOWNSHIP <b>10S</b> RANGE <b>32E</b> NMPM.		10. Field and Pool, or Wildcat <b>Mescalero San Andres</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4322 D.F.</b>		12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Clean up and stimulate production</u> <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU pulling unit, install BOP.
- 2) Pull rods & tubing.
- 3) Run tbg. & packer.
- 4) Acidize w/3000 gals. 15% NEHCL in six equal stages. Stages to be separated with 80# Graded Rock Salt and 5 ball sealers in lease crude. Acid to contain demulsifiers, surfactants and an aromatic hydrocarbon to clean up any paraffin or other heavy hydrocarbons.
- 5) Pull tbg. and packer, run tbg. and rods.
- 6) Put on production and test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles Gray TITLE Production Analyst DATE 8-26-74

Orig. Signed by

Joe D. Ramey

Dist. I. Supv. TITLE

APPROVED BY \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: