

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

AUG 26 1 22 PM '65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
State Oil & Gas Lease No.	
0 9091	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Cactus Drilling Company		8. Farm or Lease Name Atlantic State
3. Address of Operator P O Drawer 2068, Hobbs, New Mexico		9. Well No. 1
4. Location of Well UNIT CENTER A 660 FEET FROM THE N LINE AND 660 FEET FROM THE E LINE, SECTION 32 TOWNSHIP 9 N RANGE 34 E NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4275 D F		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
DRILL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging of well effected in the following manner:

Set 25 sx cement plug on bottom at 9925, set cement plug of 25 sx cement at 9050, set 25 sx cement plug at 7750, set 25 sx cement plug 6925, set 25 sx cement plug 5450, 25 sx cement plug in and out of 8-5/8" csg. shoe at 4100, set 25 sx cement plug 1230, cut-off point, set 25 sx cement plug in and out of 13-3/8" csg. shoe at 369, and 10 sx cement plug set at surface. All intervals between cement plugs filled with mud, lease cleared of all equipment, surface returned to natural contour and well marker placed for identification.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Lee M. Blaker* TITLE **Vice President** DATE **8/25/65**

APPROVED BY *Lester J. Clendenen* TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: