DISTRICT !
P.O. Box 1980, Hobbs, NM 88240

OL CONSERVATION DIVISION P.O. Box 2088

LL API N	O.		
30	025	21218	

DISTRICT II Santa Fe, New	30 025 21218	
P.O. Drawer DD, Artesia, NM 88210	WCAICO 07504-2000	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410		STATE X FEE 6. State Oil & Gas Lesse No. NM 058102
SUNDRY NOTICES AND REPORTS	ONWELLC	VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO	ON WELLS DIDEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION	N FOR PERMIT"	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOS 1. Type of Well:	ALS.)	Flying "M" (SA) Unit
OIL GAS WELL OTHER		Tract 14
2. Name of Operator		8. Well No.
Coastal Oil & Gas Corporation		4
3. Address of Operator		9. Pool name or Wildcat
P.O. Box 235, Midland, Texas 79702		Flying "M" (SA)
Unit Letter I :663 Feet From TheI	East Line and 19	79' Feet From The South Line
Section 20 Township 9-S	Range 33-E	NMPM Lea County
\/////////////////////////////////////	GR 4366'	. <i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
11. Check Appropriate Box to Ir	ndicate Nature of Notice, R	leport, or Other Data
NOTICE OF INTENTION TO:		SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	N X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS		
	COMMENCE DRILLING	
PULL OR ALTER CASING	CASING TEST AND CI	EMENT JOB L
OTHER:	_ U OTHER:	
 Describe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103. 	t details, and give persinent dates, inclu	ding estimated date of starting any proposed
NOTE: Cement was circulated to surface when (see attached wellbore diagram).	en the 4-1/2" product	ion casing was installed
l. Set CIBP at ± 4360' (perfs are 4409'-33	3').	
2. GIH with tbg, circ hole with 9.5 PPG mu	ıd.	
3. Spot 20' cmt plug on top of CIBP (3 sac	cks).	
. Spot 100' cmt plug 1900'-1800' (15 sack	cs). Base of Salt at	1850'.
5. Spot 100' cmt plug from 418'-318' (15 s	sacks) wich ne	GO TO PERL 45 8 8 E PLAN
5. Spot 30' cmt plug from 30' - surface (5	cem in	85/ am nucles -
7. Install P&A Marker. Clean and level lo		
. Install row Marker. Clean and level in	At A control of	HEREN DE NOTHED HEREN TO COMMENCING WORK
I hereby certify that the information above is true and complete to the best of my kno		
SIONATURE Dolly L Smith	sr. Petrole	Im Engineer 02/23/94
TYPE OR PRINT NAME Bobby L. Smith		<u>телерноме но 915—682—79</u> 2.
(This space for State Use)	ORIGINAL SIGNED BY DISTRICT I SUP	JERRY SEXTON FEB 28 1994
APPROVED BY	TITLE	DATE

CONDITIONS OF APPROVAL, IF ANY: