

Submit 3 Copies  
to Appropriate  
District Office.

State of New Mexico  
Energy Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-21245
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 32636
7. Lease Name or Unit Agreement Name Felmont Collier
8. Well No. 1
9. Pool name or Wildcat North Bagley, Permo Penn

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Fasken Oil and Ranch, Ltd.
3. Address of Operator 303 W. Wall, Suite 1800, Midland, TX 79701-5116	4. Well Location Unit Letter H : 1980 Feet From The North Line and 510 Feet From The East Line Section 9 Township 11-S Range 33-E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4286' KB	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-9-99: MIRU plugging equipment and plugged well as follows:

3-9-99

thru:

3-10-99: POW and lay down rods and pump. POW w/tbg. and RIW and set 5½" CIBP @ 9300'.

3-11-99: Circ well with 9.5 ppg mud-laden fluid. Spotted 25 sx of Class "H" on top of CIBP. Spotted 25 sx of Class "H" at 8700'. Spotted 25 sx of Class "H" at 7380'.

3-12-99: Tagged top of plug at 7145'. Spotted 25 sx of Class "H" at 5170'.

3-15-99: NDWH and weld on 5½" pull nipple. Installed casing jacks. Free point 5½" casing and cut off at 4097'. POW and laid down 2221.51' of 5½" Buttress casing and 1865.45' of 5½" 8rd casing.

3-16-99: Spotted 110 sx of Class "C" at 4147'. WOC 4 hrs. and tagged at 3810'. Witnessed by Bill Pritchard w/NMOCD.

3-17-99: Spotted 45 sx of Class "C" at 1803'. Spotted 10 sx of Class "C" at surface. Cut off casing 4' below surface. Weld on plate w/4" OD marker 4' above GL. Backfilled cellar, pit and removed mast anchors. Well plugged and abandoned.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Don Hillis TITLE Production Superintendent DATE 3/18/99

TYPE OR PRINT NAME Don Hillis TELEPHONE NO. 915-687-1777

(This space for State Use)

APPROVED BY Billy E. Pritchard TITLE OIL & GAS INSPECTOR DATE JUN 04 1999

CONDITIONS OF APPROVAL, IF ANY:

Jo GWW

Jo dp