

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 4-584	
7. Unit Agreement Name	
8. Farm or Lease Name Kelly State	
9. Well No. 1	
10. Field and Type of Well Scale 1st (Perm)	
11. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Midwest Oil Corporation
3. Address of Operator 1500 Wilco Bldg., Midland, Texas 79701
4. Location of Well UNIT LETTER P 660 FEET FROM THE South LINE AND 60 FEET FROM THE East LINE, SECTION 10 TOWNSHIP 105 RANGE 32E N.M.P.M.
5. Elevation (Show whether DF, RT, GR, etc.) 4218.3 GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASINGS <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASINGS <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-16-73

Well was plugged and abandoned as follows:

- 35 sks. cnt. plug set 3940' to 380'.
- 25 sks. cnt. plug set 3110' to 300'.
- 30 sks. cnt. plug set 3321' to 255'.
- 10 sks. cnt. plug set surface.
- dry hole marker installed.

(note: on 11-21-67 50 sks. plug set 3550' to 3350' - 75 sks. plug 3350' 3000') well was circulated with a full cement plug set with gelled mud. Location cleaned and ready for final inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gene Milford TITLE agent DATE 3/28/73

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: