

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. OG-5543
7. Unit Agreement Name
8. Farm or Lease Name STATE "CX"
9. Well No. 1
10. Field and Pool, or Wildcat Undesignated
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- ☐
2. Name of Operator New American Petroleum Corp.
3. Address of Operator Box 68, Hobbs, N.M. 88240
4. Location of Well UNIT LETTER H 2117.7 FEET FROM THE North LINE AND 522' FEET FROM Underdesignated THE East LINE, SECTION 18 TOWNSHIP 9-S RANGE 33-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4400' RDB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☒
OTHER **Completion** ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
**On 5-22-65, 4 1/2" OD 9.5 #J-55 casing was set at 4426' w/250 rx. Incer. Tested Casing w/1500 PSI for 30 minutes. Test O.K. Drilled out to 4429' PBD. Perforated 4398-4412' w/25PF & acidized w/750 & 2000 gallons acid. Swabbed water only. Dry hole. We propose to plug & abandon as follows: Spot 25 rx. cement plug on bottom & cover open hole interval (4431-4460) & perf. (4398-4412) back to approx. 4200'. Cut and pull 4 1/2" casing from approx. 3500'. Spot 25 rx. plug in and out of 4 1/2" stub. Spot 50 rx plugs at 2450-2550 & 1800'-1900'. Spot 25 rx. plug in and out of 8 7/8" casing at 398'. Spot 10 rx plug at surface and erect P&H marker, clean level, and restore ground to its natural contour.
TD-4460' GL-4390' RDB-4400'**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY
V. E. STALEY

SIGNED

TITLE

DATE

TITLE

DATE

(048)
013-NMCC
1-3-65
1-3-65
1-3-65

COPIES OF APPROVAL, IF ANY: