State of New Mexico

Form C-103

to Appropriate District Office	Energy, Minerals and Natural R	aoutes Department	Revised 1-1-89	
DISTRICT I P.O. Box 1980, Hobbs, NM \$8240	Santa Fe. New Mexico 87504-2088		WELL API NO.	
DISTRI CT II			30-025-21338	
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Losse STATE XX FEE	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gue Lease No.	
<u></u>	·		VA-0333 VIII	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
1. Type of Well: OR. GAS WELL X WELL	OTT-BIR.		 Shell State	
2. Name of Operator	UITER		& Well No.	
Manzano Oil Corporation 505/623-1996			1	
1. Address of Operator			9. Pool name or Wildrat	
P.O. Box 2107/Roswell 4. Well Location	NM 88202-2107		Wildcat Cuerro Largo Peni	
D 220 N H H 2210				
Unit Letter : : :	Feet From The NOT LI	LIM IM	Feet From The EdSt Line	
Section 26	Township 10 South Re	unge 32 East 1	NMPM Lea County	
	10. Elevation (Show whether		<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	
	4297'			
	Appropriate Box to Indicate 1	· · · · · · · · · · · · · · · · · · ·	•	
NOTICE OF INTENTION TO: SUBSEQUENT			SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING CPNS.			CPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING CASING TEST AND CEN			мент лов 🔲	
OTHER:		OTHER:	·	
12 Describe Proposed or Completed Operat	ions (Clearly state all persinent details as	d sine pertinent dates includ	is a enimated date of startise agreemonated	
work) SEE RULE 1103.			and commence in the same of th	
12/28/95 MICU. Rig up. MI & unload tbg. Prep to P&A well.				
12/29/95 Pick up tbg. TIH w/tbg open ended to 445'. Rig broke down. SDON.				
12/30/95 Waiting on rig repair.				
12/31/95 Waiting on rig repair.				
	SD for Sunday.			
1/02/96 SD for New Y	/02/96 SD for New Years. This a.m. hung off tbg. Will change out rig and continue			
with P&A. 1/03/96 Change out rigs. Continue in hole w/tbg to 1415'. Tag. Rotate tbg with tongs.				
	ike any progress. SION		rug. Notate the wron tongs.	
			to load hole. Circl and mix	
mud. Wash t	o 2019'. Ran tbg to 2	242' and circl.	Ran tbg to 4542' and circl.	
		. Cond mud Mu	d Wt 10, Vis 32. Pull up to	
1400'. SION	I •			
•				
Signature				
SXNATURE Alleron tiles	mr.	<u>Lnqineerinq Te</u>	echnician 1/8/96	
TYPE OR PRINT NAME Allison Her	nandez	•	тельные на 623-1996	
(This serve for Size 11m)				
	MED BY JEPRY SEXTON		JAN 12 1898	
ATTROVED BY	gradije dominizao	l	DATE	
~: == 1 LD = 1	,,, ,,, ,,,			