

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL AND GAS COMMISSION

JUL 5 10 00 AM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Stolts & Company	7. Unit Agreement Name
3. Address of Operator c/o Oil Reports & Gas Services, Box 763, Hobbs, New Mexico	8. Farm or Lease Name Bell
4. Location of Well UNIT LETTER A 554 FEET FROM THE North LINE AND 554 FEET FROM THE East LINE, SECTION 21 TOWNSHIP 11 S RANGE 33 E NMPM.	9. Well No. 2
10. Field and Pool, or Wildcat North Bagley Upper Penn	
15. Elevation (Show whether DF, RT, GR, etc.) 4276 KB	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Casing collapsed at 6438. Pulled casing from 6438 and reran 4 1/2" casing with casing bowl. Unable to latch bowl, parted casing at 5206. Pulled casing from 5206.

It is proposed to plug & abandon as follows:

Spot 100 sacks at 4 1/2" stub at 5206
Spot 25 sacks at 7 5/8" shoe at 3750
Cut & pull 7 5/8" casing from approximately 2700
Spot 25 sacks at 7 5/8" stub
Spot 25 sacks at top of Yates at 2450
Spot 25 sacks at top of Anhydrite at 1530
Spot 25 sacks at 10 3/4" shoe at 300
Spot 10 sacks at surface with regulation marker
Rotary mud between all plugs
Clear and level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. L. Smith TITLE Agent DATE 7/1/67

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: