NO. OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSER	RVATION COMMISSION	Effective 1-1-65
FILE			
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			State X Fee
OPERATOR			5. State Oil & Gas Lease No.
			E-8835
SUNDR (DO NOT USE THIS FORM FOR PRO USE "APPLICAT	Y NOTICES AND REPORTS ON WINDOWS TO DELLE TO DELLE BACKLON FOR PERMIT - " (FORM C-101) FOR SUCH F	ELLS k to a different reservoir. Proposals.)	
1. OIL X GAS WELL WELL	OTHER-		7. Unit Agreement Name
2. Name of Operator			8. Farm or Lease Name
TEXACO Inc.			New Mexico "CQ" State
3. Address of Operator			9. Well No.
P. O. Box 728 - Hobbs, New Mexico 88240			2
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER L	660 FEET FROM THE West	LINE AND 1989 FEET FROM	Inbe Permo Penn
	ON 35 TOWNSHIP 10-S		Allillillilli
15. Elevation (Show whether DF, RT, GR, etc.)			12. County
420¼ DF			Lea
16. Check	Appropriate Box To Indicate Nat	ture of Notice. Report or Ot	her Data
NOTICE OF IN	T REPORT OF:		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	<u> </u>	REMEDIAL WORK	ALTERING CASING PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	EASING TEST AND CEMENT JQB	_
OTHER		OTHER	L
work) SEE RULE 1103.	perations (Clearly state all pertinent details		g estimated date of starting any proposo

- Pull production equipment. l.
- Mud up well bore. 2.
- Spot 40 sx Plug across pay zone and up 30' above top perf. Cut off and recover 4-1/2" casing from 5000'. Cut off 7-5/8" casing at free pt.

 Spot 30 sx plugs across all stubs. 3. 4.
- 5.
- 6.
- 7.
- Spot 10 sx plug at surface.

 Install 4" Dry Hole Marker extending 4' above ground level. 8.
- Clean location. Plug and abandon. 9.

18. I hereby certify that the information above is true and		st of my knowledge and belief. Assistant District Superintendent	DATE 4-22-71
APPROVED BY Clines		SUPERVISOR DISTRICE'S	APR 2 6 1971
CONDITIONS OF APPROVAL, IF ANY:	1-7	The Itaxe	Derry 13/11

RECEIVED

APR 23 1971

OIL CONSERVATION COMM.

H03BS, N. ...

1