

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

OG 421

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator BTA Oil Producers	8. Farm or Lease Name FMS 664 Ltd.
3. Address of Operator 104 S. Pecos Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER <u>N</u> <u>660-66</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>19</u> TOWNSHIP <u>9-S</u> RANGE <u>33-E</u> NMPM.	10. Field and Pool, or Wildcat S. Flying M <u>Penn</u> <u>Bough</u>
15. Elevation (Show whether DF, RT, GR, etc.) 4374' G. L.	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed procedure:

Call NMOCC, Hobbs, (505/393-6161) 24 hrs. advance.

Hole to be filled w/mud laden fluid.

Set CIBP @ 9000' w/3 sx cmt. on top.

Cut & pull 5-1/2" csg. T/C @ 7665'. Casing bowl 6488'.

Set 50 sx cmt. @ stub.

Set 50 sx cmt. @ 5073' Glorietta.

Set 50 sx cmt. @ 3663' Base Intermediate.

Set 10 sx cmt. @ surface.

Install Dry Hole Marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James Jones TITLE Production Clerk DATE 11/1/73

APPROVED BY Joe D. [Signature] TITLE Director DATE 11/1/73

CONDITIONS OF APPROVAL, IF ANY: