

OIL CONSERVATION DIVISION

P. O. BOX 2038
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
V-483

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A WELL IN A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER-	7. Unit Agreement Name
2. Name of Operator Wilson Energy, Inc.	8. Farm or Lease Name New Mexico "I" Stat
3. Address of Operator 1450 Briercroft Savings Bldg., Midland, TX. 79701	9. Well No. 1
4. Location of Well UNIZ LETTER B, 660 FEET FROM THE North LINE AND 1978.9 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 11S RANGE 34E NMPM.	10. Field and Pool, or Wildcat Inbe Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4198 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
		re-entry ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Please See Attached Activity Report

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie W. Setay TITLE Production Supt. DATE 2/10/88

APPROVED BY Eddie W. Setay TITLE Oil & Gas Inspector DATE FEB 18 1988

CONDITIONS OF APPROVAL, IF ANY:

UNION ENERGY, INC.
ACTIVITY REPORT
NEW MEXICO STATE "1" Ho. 1
660' TBL & 1978.2 TBL (B)
Section 7, T-11 S, R 34 E
Lea County, New Mexico
In the Pough "C" Formation
Proposed ID: 9055'

- 7/23/87 - TTH w/ 3 7/8" Shoe Tag 8562' - Wash and Fill to 8615' - Plugged tubing - POOH.
- 8/11/87 - TTH w/ 3 7/8" Concave Mill and Mill Junk Iron 8595'-8600'.
- 9/01/87 - TTH w/ 3 3/4" Flat Bottom Mill - Billing Solid Junk Iron 8600' - 8615'.
- 9/18/87 - TTH w/ 3 1/2" Kutrite shoe and wash pipe - Tag fill at 8600' - Iron at 8615' cut and wash to 8620' - Wore out shoe - POOH.
- 10/02/87 - TTH w/ 3 3/4" overshot - Tag fill at 8620'. Top fish at 8620' - Latch on and Jar loose - POOH. Recovered 5' pc. Sucker rod.
- 10/24/87 - TTH w/ 3 1/2" washpipe and 3 7/8" X 2 7/8" Kutrite Shoe - Tag at 8616' - Wash and fill to 8646' - Wore out Shoe - POOH.
- 11/07/87 - TTH w/ 3 7/8" Kutrite Shoe on 29' of 3 1/2" washpipe - Mill and wash to 8650' and twisted off washpipe - POOH.
- 11/23/87 - TTH w/ Taper Tap - Tag At 8588' (top Fish at 8621') wash Fill to 8621' - Unable to latch Fish Securely - POOH.
- 12/04/87 - TTH w/ 1.920" Center Spear and 2 7/8" Joints 2 7/8" Tubing - Tag Fill @ 8618' Wash to Fish @ 8621' - Latch on and Jar on Fish - Tool Pulled off Fish - Came out of Hole and Shut Down.
- 12/24/87 - TTH w/ Lead Impression Block on tubing and Tag. Pulled out of Hole - Shut Down Weather.

