

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
RECORDS	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-
2. Name of Operator
Tipperary Oil & Gas Corporation
3. Address of Operator
P. O. Box 3179, Midland, TX 79702
4. Location of Well
UNIT LETTER A 510 FEET FROM THE North LINE AND 660 FEET FROM
THE East LINE, SECTION 21 TOWNSHIP 11S RANGE 33E NADP.

7. Unit Agreement Name
Unit
8. Farm or Lease Name
Bell
9. Well No.
3
10. Field and Pool, or Wildcat
N. Bagley Penn

15. Elevation (Show whether DF, RT, CR, etc.)
4276' KB

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in pulling unit. Pick up and ran 7295' of tubing in hole. Loaded hole with 9.5 ppg mud. Spotted 5 sacks of cement at 7295'. Attempted to pull 4-1/2" casing, unsuccessful. Spotted 25 sack plug at 5086', 3700, 2449' and 1768' inside 4-1/2" casing. Perforated 4 holes at 410'. Mix and circulate 70 sacks cement behind 8-5/8" casing. Put 5 sacks cement at top of well. Welded on plate and dry hole marker. Job completed 11/16/83.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Operations Mgr. DATE 11-17-83

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE FEB 14 1984

CONDITIONS OF APPROVAL, IF ANY: