

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Free <input type="checkbox"/>
5. State Oil & Gas Lease No.
OG - 765

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Read & Stevens, Inc.	8. Farm or Lease Name Gross
3. Address of Operator P.O. Box 2126, Roswell, New Mexico 88201	9. Well No.
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>15</u> TOWNSHIP <u>10 S</u> RANGE <u>33 E</u> NMPM.	10. Field and Pool, or Wildcat <u>Inbe</u>
11. Elevation (Show whether DF, RT, GR, etc.) 4219' KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug in the following manner:

Set a cast iron bridge plug @ 9600'
Set 35' of cement on top of the bridge plug.
Fill hole with good mud.
Set a 35 sack cement plug in 5½" @ casing stub.
Set a 35 sack cement plug @ 5330' to 5230'
Set a 35 sack cement plug @ 3965' to 3865'
Set a 56 sack cement plug in 8-5/8" casing stub.
Set a 80 sack cement plug @ 405' to 305'
Set a 10 sack cement plug @ 10' to 0'

Erect Regulation Marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE March 20, 1972

APPROVED BY Orig. Signed by Joe D. Ramsey TITLE Dist. I, Supv. DATE APR 7 1972

CONDITIONS OF APPROVAL, IF ANY: