NO. OF COPIES RECEIVED]	Form C-103
	c. c.	Supersedes Old
DISTRIBUTION		C-102 and C-103 Effective 1-1-65
SANTA FE	NEW MEXICO DIL CONSERVATION COMMISSION	
FILE	-	5a. Indicate Type of Lease
U.S.G.S.	-	State Fee.
LAND OFFICE	-	5. State Oil & Gas Lease No.
OPERATOR		
· · ·		mmmmm
SUNDI		
(DO NOT USE THIS FORM FOR PR USE "APPLICA"	RY NOTICES AND REPORTS ON WELLS toposals to drill or to deepen or plug back to a different reservoir. tion for permit	7. Unit Agreement Name
I. OIL GAS WELL WELL	OTHER- WILDCAT	
2. Name of Operator		8. Farm or Lease Name
ROBERT N. ENFIELD	MEDLIN	
3. Address of Operator	9. Well No.	
P.O. Box 807, Roswell	1	
4. Location of Well		10, Field and Pool, or Wildcat
	660 South 660	WILDCAT
UNIT LETTER	660 FEET FROM THE South LINE AND 660 FEET FR	
THE East LINE, SECT	10N 28 TOWNSHIP 9(South) RANGE 34 (East) NMI	~~
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
	4254 DF	LEA AIIIIII
^{16.} Check	Appropriate Box To Indicate Nature of Notice, Report or (Other Data
	INTENTION TO: SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	
	OTHER	
01HER		
17. Describe Proposed or Completed (work) SEE RULE 1103.	Operations (Clearly state all pertinent details, and give pertinent dates, includ	ling estimated date of starting any proposed
	abandon and mill & 5/08 agains on falloums	
intend to plug and	abandon and pull 8-5/8" casing as follows:	
1. Spot 25 sack ce	ement plugs as follows:	
9800-99001. 885	50-89501, 6795-68951, 5260-53601, 4035-41251.	

2. Shoot off and pull 8-5/8" casing at 2500" or above.

3. Spot cement plugs as follows:

25 sacks in and out of 8-5/3" stub 25 sacks in and out of 13-3/8" casing (set at 339") 10 sack plug at surface

4. Spot drilling mud between plugs.

5. Erect dry hole marker.

6. Fill and level pits and clean location.

SIGNED N. Lee Harrard	CEOLOGIST-ENGINEER	DATE 10-10-66
	and the All Articles	
APPROVED BY	TITLE	DATE