

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-7324	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Clar-Don Products Company		State
3. Address of Operator		9. Well No.
o/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, N. M. 88240		1
4. Location of Well		13. Field and Pool, or Wildcat
UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM		Inbe Permo Penn
THE West LINE, SECTION 14 TOWNSHIP 10 S RANGE 33 E NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4213 RKB		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set Cast Iron Bridge Plug @ 9627, cap with 35' on top of plug.
Shot 5 1/2 casing at 8511' and pulled
Run in with tubing to 6217 unable to circulate deeper
Spot 390' cement plug from 6217-5827 (130 sks)
Spot 200' cement plug across top Glorieta @ 5307 (100 sks - 5257-5357)
Spot 100' cement plug across 8 5/8 casing shoe @ 3975 (60 sks - 3925-4025)
Shot 8 5/8 casing at 3000' and 1182 and pulled
Spot 100' cement plug across 8 5/8 casing stub at 1182 (72 sks - 1132-1232)
Spot 100' cement plug across 13 3/8 casing shoe @ 405 (75 sks - 355-455)
10 sacks @ surface with regulation marker.
Mud between all plugs. P&A 12/21/73

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Harold Miller</u>	TITLE <u>Agent</u>	DATE <u>1/31/74</u>
APPROVED BY <u>Edith A. Long</u>	TITLE <u>Agent</u>	DATE <u>1/31/74</u>
CONDITIONS OF APPROVAL, IF ANY:		