

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

MAR 2 1 09 PM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Sawyer
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator Jack Grynberg
3. Address of Operator 750 Petroleum Club Bldg., Denver, Colorado
4. Location of Well UNIT LETTER <u>6</u> , <u>330</u> FEET FROM THE <u>north</u> LINE AND <u>1650</u> FEET FROM THE <u>west</u> LINE, SECTION <u>24</u> TOWNSHIP <u>9 S</u> RANGE <u>36 E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4036' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled 4125.77' 4 1/2" csg.
Pulled 1206.06' 8 5/8" csg.
Plugs set at the following intervals:
25 sx. @ 70
25 sx. @ 11,840
25 sx. @ 9,700
25 sx. @ 9,140
25 sx. @ 7,740
25 sx. @ 6,972
75 sx. @ 5,350

Set cast iron plug @ 4850'. Put 35 sx. cement on plug.
25 sx. @ 4,115
25 sx. @ 1,200
25 sx. @ 430
10 sx. @ surface, Installed dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jack Grynberg TITLE Owner DATE February 27, 1967

APPROVED BY John W. Runyan TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: