

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-21889
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-2604
7. Lease Name or Unit Agreement Name Bagley-State
8. Well No. 1
9. Pool name or Wildcat Bagley Permo Penn, North

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Sabre Operating Inc.	
3. Address of Operator P.O. Box 4848 Wichita Falls, Tx 76308	
4. Well Location Unit Letter <u>H</u> : 1980' Feet From The <u>North</u> Line and 660 Feet From The <u>East</u> Line Section 16 Township 11S Range 33E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4283' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NOTIFY CONSERVATION COMMISSION 24HRS. BEFORE OPERATIONS BEGIN (505)393-6161

- (1) Well TA 6/1/7/91 CIBP set @ 8600' w/2 sx. cmt. (C-103 Attached)
- (2) Circ hole w/mud laden fluid.
- (3) 25sx. 6200' in 5½" csg.
- (4) 50sx. 5½" stub plug apprx. 5000'.
- (5) 50sx. 8-5/8" shoe plug 3850-3750' (WOC-TAG).
- (6) 50sx. 8-5/8" stub plug apprx. 700'
- (7) 80sx. 13-3/8" shoe plug 425-325' (WOC-TAG)
- (8) 20sx. 30-0'
- (9) Install hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Frelan Fields TITLE Agent DATE 2/13/96
TYPE OR PRINT NAME Frelan Fields (915) 366-1852 TELEPHONE NO.

(This space for State Use)

APPROVED BY ENTRUSTED SIGNATURE TITLE DATE FEB 20 1996

CONDITIONS OF APPROVAL, IF ANY:

2/13/96