

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>K-2604</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>United States Smelting Refining and Mining Company</b>	8. Farm or Lease Name <b>Bagley-State</b>
3. Address of Operator <b>Post Office Box 1877, Midland, Texas 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>H</b> <b>660</b> FEET FROM THE <b>East</b> LINE AND <b>1980</b> FEET FROM THE <b>North</b> LINE, SECTION <b>16</b> TOWNSHIP <b>11-S</b> RANGE <b>33-E</b> NMPM.	10. Field and Pool, or Wildcat <b>North Bagley</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4273' GR</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 2:00 P.M. 10-18-66. Set 13 3/8" 48# H-40 casing at 364', cemented w/400 sacks 50-50 pozz / 27 CaCl plug down 10:15 A.M. 10-19-66. WOC 12', tested casing w/600 psi for 30" ok. Set 8 5/8" casing at 3799' cemented w/350 sacks 50-50 pozz. Plug down 11:00 P.M. 10-23-66. WOC 24 hours, tested casing w/1000 psi for 30", ok.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *O. L. Davis* **O. L. Davis** TITLE **Production Clerk** DATE **Oct. 25, 1966**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: