NO. OF COPIES RECEIVED		
	UNDER STROP & S A	Form C-103
DISTRIBUTION	HOBES OFFICE O. C. C. HOBES OFFICE O. C. C.	Supersedes Old
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 11 65
FILE	JAN 19 152 AN 67 JAN 15 8 11 AM '67	
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State 📕 🛛 Fee.
OPERATOR		5. State Oil & Gas Lease No.
· · · · · · · · · · · · · · · · · · ·		K-2675
SUND (DO NOT USE THIS FORM FOR P USE "APPLIC	DRY NOTICES AND REPORTS ON WELLS roposals to drill or to deepen or plug back to a different reservoir. Ation for permit -" (form C-101) for such proposals.)	
I. OIL GAS WELL WELL	OTHER-	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Nidmast 011 Corporation		New Nexico "A" State
3. Address of Operator		9. Well No.
1500 Wilco Bldg. 1	tidiané, Taxas	1
4. Location of Well		10. Field and Pool, or Wildcat
	660 FEET FROM THE LINE AND FEET FR	Middle Lane (Penn)
THE LINE, SEC	TION 14 TOWNSHIP 10-S RANGE 33-E NMS	
THE WOOL LINE, SEC		
16. Check	TION 14 TOWNSHIP 10-S RANGE 33-E NMI 15. Elevation (Show whether DF, RT, GR, etc.) 4206.2 GL Appropriate Box To Indicate Nature of Notice, Report or G	2M. 12. County Les
16. Check NOTICE OF PERFORM REMEDIAL WORK	10 10-S NME 15. Elevation (Show whether DF, RT, GR, etc.) 4206.2 GL 4206.2 GL Appropriate Box To Indicate Nature of Notice, Report or O INTENTION TO: PLUG AND ABANDON Remedial work COMMENCE DRILLING OPNS.	Deter Data
16. Check NOTICE OF	10-\$ 10-\$ 33-\$ NMI 15. Elevation (Show whether DF, RT, GR, etc.) 4206.2 GL 4206.2 GL 4206.2 GL SUBSEQUE PLUG AND ABANDON REMEDIAL WORK	DM. 12. County Lee Other Data NT REPORT OF: ALTERING CASING
16. Check NOTICE OF PERFORM REMEDIAL WORK	10-S 33-E NME 15. Elevation (Show whether DF, RT, GR, etc.) 4306.2 GL 4306.2 GL 4306.2 GL 4306.2 GL SUBSEQUE PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS OTHER OTHER Operations (Clearly state all pertinent details, and give pertinent dates, included) And give pertinent dates, included)	DM. 12. County Lee Other Data NT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
16. Check NOTICE OF PERFORM REMEDIAL WORK TEMPORARIL (ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed work) SEE RULE 1103. Bpudded 11-21-66. Ref	10-\$ 10-\$ 33-\$ NMI 15. Elevation (Show whether DF, RT, GR, etc.) 4206.2 GL 4206.2 GL 4206.2 GL 4206.2 GL SUBSEQUE NTENTION TO: SUBSEQUE Plug and abandon Remedial work CHANGE PLANS Change plans OTHER	Den. 12. County Lee Dther Data NT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT ing estimated date of starting any propose 329 sex reguler

11-29-66: Ran 129 jts. 8 5/8" csg. set @ 4004'. Command with 350 sax regular most commant plus 150 sax class C plus 2% cc. WOC 16 hrs. Tasted csg. 1000# - tested GK.

12-29-66: Ran 304 jts 54" csg to 9787 comented with 375 sax 50-50 Posmix with 2% jel and 109 salt per sax. NOC 24 hrs. Ran tamp. survey - top of coment is \$120'. Tested csg to 4000# tested OK.

18, I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED		DATE	
APPROVED BY	TITLE	DATE	