DISTRIBUTION SANTA FE		Form C-103
SANTA FF	HARBS OFFICE 6. 6. 6.	Superstitles wid C-102 and C-103 FFICE O. C. C.
JANTA TE	NEW MEXICO OIL CONSERVATION COMMISSION. G. C.	Effective 1-1-65
FILE	In 10 1 or PM 167	JAN 17 11 15 11 15
U.S.G.S.		5a. Indicate Type of Le46
LAND OFFICE		State X Fee
OPERATOR		5. State Oil 5338 ease No.
		······
SUND (DO NOT USE THIS FORM FOR F USE "APPLIC	ORY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ATION FOR PERMIT -'' (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL X GAS		7. Unit Agreement Name
2. Name of Operator	OTHER-	8. Farm or Lease Name Harris-State
Pennzoil Company		
3. Address of Operator 1007 Midland Savia	ngs Building, Midland, Texas	9. Well No. 1
4. Location of Well	2086 SEET FROM THE South LINE AND 554	10. Field and Pool, or Wildcat Undesignated
UNIT LETTER $f L$,	FEET FROM THE LINE AND FEET FROM	
THE West LINE, SEC	TION 5 TOWNSHIP 11-S RANGE 34-E NMPM	
	15. Elevation (Show whether DF, RT, GR, etc.) 4196 GL	12. County Lea
16. Check	Appropriate Box To Indicate Nature of Notice, Report or Or	ther Data
		T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
		
	OTHER	
OTHER	OTHER	
17. Describe Proposed or Completed work) SEE RULE 1103.	Operations (Clearly state all pertinent details, and give pertinent dates, includin	g estimated date of starting any proposed
17. Describe Proposed or Completed work) SEE RULE 103. 11-25-66 - Spud 11-26-66 - Dril Cmtd w/29 Test 12-3-66 - Dril Cemt w/8# surv		csg to 387' Sx regular neat Cement circulated sted o.k. WOC 12 hrs. 32# csg to 4040'. Sx Incor neat can temperature
17. Describe Proposed or Completed work) SEE RULE 1603. 11-25-66 - Spuce 11-26-66 - Dril Cmt. Cmt. Cmt. Cmt. Cmt. Cmt. Cmt. Cmt.	Operations (Clearly state all pertinent details, and give pertinent dates, including 17½" hole at 6:00 p. m. 1ed 17½" hole to 390' - Ran 13-3/8", 48# 2 w/240 Sx regular neat w/6% gel plus 100 3 HA-5. Plug down at 11:00 a.m. 11-26-66 3 ced csg to 500# before drilling plug. Telled 11" hole to 4040'. Ran 8-5/8" 24# 50 3 c w/515 Sx Incor neat w/4% gel, plus 100 4 salt per Sx. Plug down at 8:30 p.m. Royey. Top cement 2260'. WOC 24 hrs. 3 ced csg w/1500# for min. Tested O.K.	csg to 387' Sx regular neat Cement circulated sted o.k. WOC 12 hrs. 32# csg to 4040'. Sx Incor neat can temperature

CONDITIONS OF APPROVAL, IF ANY: