

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-2443
7. Unit Agreement Name
8. Farm or Lease Name Lane State
9. Well No. 1-Y
10. Field and Pool, or Wildcat Vada Penn
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Amini Oil Corporation
3. Address of Operator 400 Wall Towers West, Midland, Texas 79701
4. Location of Well UNIT LETTER <u>M</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>760</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>10-S</u> RANGE <u>34-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) DF 4254

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JQB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 11-16-71 Moved in casing pulling unit. Spotted 90 sk plug @ 9980, and fill hole w/mud.
- 11-17-71 Weld 5 1/2" pull nipple on, set sub-structure, work on slips wouldn't come, shut down.
- 11-18-71 Pull slips, shot csg @ 6485', would not come, shot @ 4005', Pull 20', stuck, work csg.
- 11-19-71 Pulled 5 1/2" csg. set 50 sk cement plug @ 4005 - 5 1/2" stub.
- 11-20-71 Shot 8 5/8" csg @ 1238 worked csg, didn't come, shot @ 1021 pulled csg., set 25 sk plug @ 1021 - 8 5/8" stub. set 25 sk plug @ 360'.
- 11-22-71 Set 10 sx cement plug in tar of 11 3/4" surface casing, and installed marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Karin Holman</u>	TITLE <u>Agent</u>	DATE <u>1-5-72</u>
APPROVED BY <u>John W. Remyan</u>	TITLE <u>Geologist</u>	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

FEB 17 1972

OIL CONSERVATION COMM.
HOBB, N. M.