

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

**CONSERVATION DIVISION**  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
K-169

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
1. Name of Operator Spence Energy Company		8. Farm or Lease Name Patton "5" State
2. Address of Operator 4849 Greenville Avenue, #381, Dallas, Texas 75206		9. Well No. 1
3. Location of Well UNIT LETTER <u>L</u> <u>660</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>5</u> TOWNSHIP <u>9S</u> RANGE <u>32E</u> NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4413 GL                      4423 KB		12. County Lea

**Check Appropriate Box To Indicate Nature of Notice, Report or Other Data**

**NOTICE OF INTENTION TO:**

**SUBSEQUENT REPORT OF:**

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Completion Attempts and plug back operations</u> <input checked="" type="checkbox"/>

**7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.**

3/30 Ran Dresser-Atlas 5½" casing gun. Perforated ABO formation 8174' to 8178' and 8207' to 8217' with one jet shot per foot. Western Co. acidized perfs with 1000 gallons 7½% Spearhead acid at 4.6 BPM at 5200#. ISIP 4400#, 15" SIP 4200#. Swabbed back load and swabbed dry. Set CIBP at 8100' with 35' cement plug on top; set 35' cement plug at 6000'. Permission to do so obtained verbally from Mr. Seay, March 30. Prep. to attempt shallower completion.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. Carroll Staton TITLE Exploration Manager DATE 3/31/83

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

**APR 11 1983**

PROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

RECEIVED  
APR 8 1983  
HOLDS OFFICE