

Form 3160-5
(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985
LIST DESIGNATION AND SERIAL NO.

NM044216 C

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		5. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR PLAINS PETROLEUM OPERATING COMPANY		7. UNIT AGREEMENT NAME	
3. ADDRESS OF OPERATOR 415 W. WALL, SUITE 1000 MIDLAND, TX 79701		8. FARM OR LEASE NAME Bluitt 24 "C" Federal	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit Letter C - 660' FNL & 1980' FWL		9. WELL NO. 3	
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT Bluitt San Andres Assoc.	
15. ELEVATIONS (Show whether OF, RT, CR, etc.) 3993 GL		11. SEC., T., R., W., OR BLK. AND SURVEY OR AREA Sec. 24, T8S, R37E	
		12. COUNTY OR PARISH Roosevelt	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

4-12-94 - Set CIBP @ 4735' w/2 sx cmt. Perforate 1 JSPF @ 4618' - 4674'. 0.36 EHD, 14.6 GM charges 14.8" cmt penetration.

4-13-94 - Acidize 1st setting 4674'-92', break @ 3600 psi, pump 3 bbl acid; 2nd setting 4649'-42', break @ 2300 psi, pump 4 bbl. 3rd setting 4626' break @ 1200 psi, pump 2 bbl. 4th setting 4636'-38', break @ 3250 psi; 5th setting 4618'-23', break @ 2000 psi & pump all acid & flush RD charger.

4-21-94 - Sand frac w/30# borate x-link gel as follows: 5000 gal pad, 3700 psi; 2000 gal w/1 PPG 20/40 sd, 3600 psi; 1260 gal w/ 2 PPG 20/40 sd, 3600 psi; 2000 gal w/3 PPG 16/30 sd, 3600 psi; 2000 gal w/4 PPG 16/30 sd, 3800 psi; 882 gal flush, 4100 psi. ATP 3600 psi, AIR 12 BPM, ISDP 1900 psi, 5 mins 1600 psi, 10 mins 1400 psi, 15 mins 1250 psi.

5-2-94 - SI waiting on Warren to install meter run.

API No. 30-041-00221

18. I hereby certify that the foregoing is true and correct

SIGNED

Bonnie Husband

TITLE

Administrative Assistant

DATE

7-29-94

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
PETER W. CHESTER

AUG 2 1994

*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE CENTER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.