

DISTRICT I
P.O. Box 1982, Hc , NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO.	30-005-00691
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	004320

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name HONDO HOLLOWAY STATE
2. Name of Operator Fi-Ro Corporation	8. Well No. 1
3. Address of Operator P O BOX 8148, Roswell, N.M. 88202	9. Pool name or Wildcat Caprock Queen
4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>36</u> Township <u>12S</u> Range <u>31E</u> NMPM County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/4/94 Rig up L&R Well Service @7:00AM. Unseat pump. pump was swabbing and rig up I&W Hot oil truck and heat 20 Bbl. of fresh water and pump down tubing. Lost pressure when 10 Bbl. down tubing. Pull rods and pump. Rig up to reverse circulate and wash out 45' of sand. Wash up surface. Rig up swab. Swab into tank battery to clean up anulas and tubing. Pull tubing and run packer. Seat packer at 2900'. Pump 500 gal. MPA and chase with KCL (2%) H2O. Pull tubing, remove packer and run tubing to TD. Put on pump. Change out electric motor and gas engine. Lay new line from pole to motor. Call Lea Co. Electric due to line problem. LeaCo changed out transformers and fuses.

(See next Page)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE 11/14/94
TYPE OR PRINT NAME Fi-Ro Corp. Tommy McDonald TELEPHONE NO 505-624-2615

(This space for State Use)

APPROVED BY JOSEPH SEXTON
DISTRICT SUPERVISOR

APPROVED BY TITLE DATE NOV 17 1994
CONDITIONS OF APPROVAL, IF ANY.