

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Enr , Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-01065
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-10706

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL ☐ GAS WELL ☐ TA'D ☐ OTHER ☐
------------------	--

2. Name of Operator	Amerada Hess Corporation
---------------------	--------------------------

3. Address of Operator	Drawer D, Monument, New Mexico 88265
------------------------	--------------------------------------

4. Well Location	Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line
Section	26
Township	12S
Range	33E
NMPM	
Lea	
County	

10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4251' DF
--	----------

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-26-90 Thru 11-2-90

MIRU Baber Well Svc. plugging unit. TIH w/5-1/2" gauge ring, unable to work tools below 7860'. Ran 2-3/8" TBG. Set OE'D at 8671' & spotted 50 sks. class C neat cement plug. Pulled up hole & WOC. Ran TBG. & checked top of cement plug at 8364' for 307' plug fr. 8671' - 8364'. Displaced hole w/mud. Spotted 10 sks. cement to bring bottom hole plug up to 8330' to cover Penn & Wolfcamp Zones. Pulled TBG. nipples down CSG. head & welded on 5-1/2" pull nipple. Removed CSG. slips & free pointed 5-1/2" CSG. Shot CSG. at 3857'. Pulled & laid down 110 JTS. 5-1/2" CSG. TIH w/TBG. to 5300' & spotted 25 sks. cement plug across San Andres Zone. Pulled TBG. to 3910' & spotted 60 sks. cement plug, 50' in & 50' out of 5-1/2" CSG. stub. Pulled up hole & WOC. Ran TBG. & checked top of stub plug at 3724' for 53' in 5-1/2" CSG. & 133' out 5-1/2" CSG. Spotted 25 sks. cement plug at 1865' at top of salt section Laid down TBG. & cut off well head. Spotted 10 sks. cement plug at surface & installed dry hole marker. RD plugging unit, cut off dead man anchors & cleaned location. Well P&A'D.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	R. L. Wheeler, Jr.	TITLE	Supv. Adm. Svc.	DATE	11-7-90
TYPE OR PRINT NAME	R. L. Wheeler, Jr.	TELEPHONE NO.	393-2144		

(This space for State Use)

APPROVED BY	Jack Griffin	TITLE		DATE	NOV 27
CONDITIONS OF APPROVAL, IF ANY:					