NO. OF COPIES RECEIVED DISTRIBUTION SANTA FE FILE	NEW MEXICO OIL CONSERVATION COMMISSION		Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65
U.S.G.S. LAND OFFICE OPERATOR			State X Fee 5. State Oil & Gas Lease No. K-29
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.) 1.			7. Unit Agreement Name
OIL GAS WELL OTHER. OWDD			8. Farm or Lease Name
Ernest A. Hanson 3. Address of Operator			Ranger
P. O. Box 1515, Roswell, New Mexico			9, Well No.
4. Location of Well UNIT LETTER H . 1980 FEET FROM THE NORTH LINE AND 660 FEET FR			10. Field and Pool, or Wildcat Wildcat
	n 15 township 12-S		
15. Elevation (Show whether DF, RT, GR, etc.)			12. County
	4170'		Lea
Check A	Appropriate Box To Indicate N TENTION TO:	-	ther Data NT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	PLUG AND ABANDON X	REMEDIAL WORP. COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER	ALTERING CASING PLUG AND ABANDONMENT
1. 25 sx. ci 2. 25 sx. ci 3. 25 sx. ci 4. 25 sx. ci 5. 25 sx. ci 6. 25 sx. ci 7. 10 sx. ci A regulation dry prior to final	to plug and abandon i at the following int. plug @ total deput. plug @ Top of Peut. plug @ Top of Wont. plug @ Top of Abut. plug @ Top of Glut. plug @ Top of Glut. plug in-and-out. plug @ surface. The plug @ surface. The plug and abandon int. plug @ Top of Peut. plug @ Top of Glut. plug @ Top of Glut. plug in-and-out. plug @ surface. The plug and abandon in the plug @ Top of Peut. plug @ Top of Glut. plug @ Surface. The plug and abandon in the plug @ Top of Peut. plug @ Top of Wont. plug @ Top of Glut. plug @ Surface. The plug and abandon int. plug @ Top of Peut. plug @ Top of Wont. plug @ Top of Wont. plug @ Surface. The plug and abandon int. plug @ Top of Peut. plug @ Top of Wont. plug @ Top of Glut. plug @ T	th 12,940°. nnsylvanian @ 10,00 lfcamp @ 9,173°. o @ 7,752°. orietta @ 5600°. of 8-5/8" csg. @ 42 e erected and the 1 OCC. John Runyan, NMOCC,	25°. coation cleaned up Hobbs, to plug
18. I hereby certify that the information	above is true and complete to the best o	f my knowledge and belief.	
SIGNED Harry & So	heard TITLE EX	ploration Manager	DATE Oct. 9, 1968
APPROVED BY	the TITLE	. •	DATE
CONDITIONS OF APPROVAL, IF ANY			