

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION
 Orig³cc: OCC, Hobbs
 cc: Southern Region (West Texas.)
 cc: Bartners
 cc: file

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Rosa Shults
9. Well No. 3
10. Field and Pool, or Wildcat Gladiola Devonian
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Sinclair Oil Corporation Merged Into Atlantic Richfield Company effective 1-1-69
2. Name of Operator SINCLAIR OIL CORPORATION
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER <u>K</u> <u>2310</u> FEET FROM THE <u>West</u> LINE AND <u>1650</u> FEET FROM THE <u>South</u> LINE, SECTION <u>18</u> TOWNSHIP <u>12S</u> RANGE <u>38E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3873' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Completed in Devonian perfs. 11,931-11,939'. TD 11,957'. PBTD 11,956'.
 13-3/8"OD casing set @ 325' and cemented w/350 sks. to surface.
 8-5/8"OD casing set @ 4625' and cemented w/2200 sks. Circulated to surface.
 5-1/2"OD casing set @ 11,957' and cemented w/200 sks. Top cement behind 5-1/2"OD csg. @ 11075'.

PROPOSE TO PLUG AND ABANDON AS FOLLOWS:

Fill hole w/heavy mud laden material.
 Set CIBP @ approx. 11,930' w/2 sks. cement on top.
 Cut 5-1/2"OD csg @ approx. 11,000' and pull.
 Spot 25 sks. cement plug top of 5-1/2"OD csg. stub.
 Spot 35 sks. cement plug top of Penn @ 9530'.
 Spot 35 sks. cement plug top of Wolfcamp @ 9093'.
 Spot 35 sks. cement plug top of Abo @ 7822'.
 Spot 35 sks. cement plug top of Glorieta @ 5908'.
 Spot 25 sks. cement plug bottom of 8-5/8"OD csg. @ 4625'.
 Spot 10 sks. cement plug top of 9-5/8"OD csg. and cellar, install regulation dry hole marker,
 clean and level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Superintendent DATE 3-4-69
 APPROVED BY [Signature] TITLE _____ DATE _____
 CONDITIONS OF APPROVAL, IF ANY: