Hara artics occ

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved thould be followed, and work should not begin until approval is obtained. See additional instructions in the Pulse and Pagulations of the Commission.

				and the second s	
OTICE OF INTENTION CHANGE PLANS		Notice of Intention to Temporarily Abandon Weli		Notice of Intention to Drill Dreper	
TICE OF INTENTION PLUG WELL		Notice of Intention to Plug Back		Notice of Intertion to Set Lines	
OTICE OF INTENTION SQUEEZE		Notice of Intention to Acidize	x	Notice of Intention to Shoot (Nitt)	
otice of Intention Gun Perforate	x	Notice of Intention (Other)		Notice of Intertion (Other)	
IL CONSERVATION (Robbs, New	Mexico	· · · · · · · · · · · · · · · · · · ·	23, 196
		(Place)		(Date)	
ntlemen:					
lair 011 & G	Company or Operator	Barnes & Go	lden	Well No. 2 in Bronco Siluro Devonien	K (Halt)
ne 4 sa	14 of Sec. 11	13 g 3	8 NMPM	Bronco Siluro Devonian	Come
		•	•	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
		inty.			
	FUL (FOLLOW	L DETAILS OF PROPOSI INSTRUCTIONS IN THE R	ULES AND	REGULATIONS)	
	FUE (FOLLOW To dual ce Perforate these per	L DETAILS OF PROPOSI INSTRUCTIONS IN THE R mplete well in th the Mississippi 2 forations with 50	e Missione from	REGULATIONS) SSIPPI Zone. B 11096-11116 and	
ROPOSE TO:	FUE (FOLLOW To dual ce Perforate these per	L DETAILS OF PROPOSI INSTRUCTIONS IN THE R mplete well in th the Mississippi 2 forations with 50	e Missione from OC galle	ssippi Zone. m 11096-11116 and ons acid. ng from the Devoni	ian Zon
ROPOSE TO:	FUE (FOLLOW To dual ce Perforate these per	L DETAILS OF PROPOSI INSTRUCTIONS IN THE R mplete well in th the Mississippi 2 forations with 50	e Missione from OC galle	ssippi Zone. m 11096-11116 and ons acid.	ian Zon
ROPOSE TO:	FUE (FOLLOW To dual ce Perforate these per	L DETAILS OF PROPOSI INSTRUCTIONS IN THE R mplete well in th the Mississippi 2 forations with 50	e Missione from OC galle	ssippi Zone. m 11096-11116 and ons acid. ng from the Devoni	ian Zon
PROPOSE TO:	FUE (FOLLOW To dual ce Perforate these per	L DETAILS OF PROPOSI INSTRUCTIONS IN THE R mplete well in th the Mississippi 2 forations with 50 .s well presently	e Missione from 00 galle product	ssippi Zone. m 11096-11116 and ons acid. ng from the Devoni lair Oil & Gas Con Company of Operator Dist. Supt.	ian Zone
PROPOSE TO:	FUL (FOLLOW) To dual co Perforate these per	L DETAILS OF PROPOSI INSTRUCTIONS IN THE R mplete well in the the Mississippi 2 forations with 50 .s well presently	e Missione from 00 galle product	ssippi Zone. m 11096-11116 and ons acid. Ing from the Devoni	ian Zono
PROPOSE TO:	FUL (FOLLOW) To dual co Perforate these per	L DETAILS OF PROPOSI INSTRUCTIONS IN THE R mplete well in the the Mississippi 2 forations with 50 .s well presently	e Missione from 600 gallo produci	ssippi Zone. m 11096-11116 and ons acid. ng from the Devoni lair Oil & Gas Con Company of Operator Dist. Supt.	ian Zon