

APR 11 REC'D

CEMENTING AFFIDAVIT

May 25, 1972

MAP 10000

CARDINAL CHEMICAL, INC.

Monahans Station, P. O. Box 686, Monahans, Texas

County of Roosevelt State of New Mexico

I N. G. Thompson did cement on Southwestern Ntl Gas Co.
Lease W. S. Federz ²⁷ Well no. 1 on 3/4/69
with Spotted 50 sacks class "H" cement plug to 4000'

An Estimate of _____ sacks were circulated to the surface.

Signed *N. G. Thompson*

Before me the undersigned notary public in and for Ward
County, State of Texas this day personally appeared
before me N. G. Thompson known to me to be the person
whose name is subscribed to the foregoing instrument and acknowledge
to me under oath that the statements contained herein are true and
correct.

Subscribed and sworn to before me this 8 day of March A.D. 19 69

J. G. Smith Notary Public
County of Ward State of Texas

Seal

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Western States Producing Company

3. ADDRESS OF OPERATOR
900 Building of the Southwest Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface 1980' FNL & 660' FWL

6. LEASE DESIGNATION AND SERIAL NO.
NB 0533777-C

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal "24"

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Chavero

11. SEC. T. R. OR BLM. AND SURVEY OR AREA
Sec. 24, T-7-S, R-32-E

12. COUNTY OR PARISH
Roosevelt

13. STATE
New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, RT, GR, etc.)
4460' KDB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pump 50 sack plug down 4 1/2" casing and displace to 4,000'.
2. Free point casing and shoot off at approximately 3700'.
3. Spot 50 sack plug from 3700' to 3500'.
4. Spot 50 sack plug from 1870' to 1730'.
5. Spot 10 sack plug at surface, remove casing head and set marker.

This well is to be abandoned due to 100% water production from the San Andres pay zone.

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

TITLE

APPROVED

FEB 13 1969

ARTHUR R. BROWN
DISTRICT ENGINEER

DATE 2/11/69

DATE

*See Instructions on Reverse Side