

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Durwood XW
3. Address of Operator 105 So. 4th St., Artesia, NM 88210	9. Well No. 1
4. Location of Well UNIT LETTER P 990 FEET FROM THE South LINE AND 330 FEET FROM THE East LINE, SECTION 18 TOWNSHIP 7S RANGE 32E NMPM.	10. Field and Pool, or Wildcat Tomahawk SA
15. Elevation (Show whether DF, RT, GR, etc.) 4448' GR	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPHS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Plugged well as follows:

Set CIBP at 3975' w/35' cement on top.

Spot 25 sx cement plug at 3415'.

RIH on wireline and could not go below 1725'. After consulting with Jerry Sexton, NMOCD, Hobbs, cut 4-1/2" casing at 1696 and pulled 1702.35'.

Spot 50 sx cement plug at 1725'. Tag plug at 1562'.

Install 10 sx cement surface plug.

Weld on plate and dry hole marker.

Used heavy mud between plugs.

Plugging completed 4-10-87.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Janita Doellett* TITLE Production Supervisor DATE 4-14-87

APPROVED BY *Jack Griffin* TITLE OIL & GAS INSPECTOR DATE JAN 04 1989

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
APR 16 1987
OCD
HOBBS OFFICE