

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-2118

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Charles B. Gillespie, Jr.
3. Address of Operator P. O. Box 8 Midland, Texas 79702
4. Well Location Unit Letter <u>D</u> : <u>800</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>3</u> Township <u>15S</u> Range <u>33E</u> NMPM Lea County

7. Lease Name or Unit Agreement Name State 'G'
8. Well No. 7
9. Pool name or Wildcat Saunders Permo Upper Penn

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4206' DF
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/01/89: Set cast iron bridge plug at 9757'.
Dumped 4 sx cement on top of bridge plug.

9/07/89: Ran 2 3/8" tubing to 9720', tagged plug.
Mixed 10 ppg mud and displaced hole.

9/08/89: Mixed and pumped 25 sx cement at 7700'.

9/11/89: Cut off and pulled 5 1/2" casing from 6006'.

9/12/89: Mixed and pumped 25 sx cement at 6060' across 5 1/2" casing stub.
Tagged plug at 5950'.
Mixed and pumped 30 sx cement at 4200'.

9/13/89: Tagged plug at 4092'. Cut off wellhead. Cement had been circulated behind 8 5/8" casing.

9/14/89: Mixed and pumped 30 sx cement at 2400'.
Mixed and pumped 30 sx cement at 300'.
~~Mixed and pumped 10 sx cement at surface. Welded 4" marker to surface pipe, cleaned~~

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David W. Hastings TITLE Production Manager DATE 3/5/90

TYPE OR PRINT NAME David W. Hastings TELEPHONE NO. (915)683-1765

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE MAY 31 1991

CONDITIONS OF APPROVAL, IF ANY:

R N

4