

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION  
 Orig & 2cc: OCC, Hobbs, N.M. 11 30 1967  
 cc: Regional Office  
 cc: Partner  
 cc: file

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

5a. Indicate Type of Lease  
 State  Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL  GAS WELL  OTHER: Plug and Abandon

2. Name of Operator: Sinclair Oil & Gas Company

3. Address of Operator: P. O. Box 1920, Hobbs, New Mexico 88240

4. Location of Well  
 UNIT LETTER E 1980 FEET FROM THE North LINE AND 900 FEET FROM  
 THE West LINE, SECTION 26 TOWNSHIP 16S RANGE 35E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name: Haddon "C" WN

9. Well No.: 2

10. Field and Pool, or Wildcat: Shoe Bar Penn

15. Elevation (Show whether DF, RT, GR, etc.)

12. County: Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-2-67 Pulled tubing and spotted 50 sacks cement plug @ 9542'. Filled hole w/heavy mud to between all plugs. Cut and pulled 4572' of 5-1/2"OD casing. Spot 25 sacks cement plug in top of 5-1/2"OD casing stub @ 4572'. Spot 10 sacks cement plug @ surface and set regulation marker, clean and levelled location. Plugged and Abandoned eff: 5-2-67

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: [Signature] TITLE: Superintendent DATE: 5-10-67

APPROVED BY: [Signature] TITLE: Geologist DATE: FEB 2 1973

CONDITIONS OF APPROVAL, IF ANY: