

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- "SWD"		5. State Oil & Gas Lease No. B-2330
2. Name of Operator Jake L. Hamon		7. Unit Agreement Name
3. Address of Operator P. O. Box 663, Dallas, Texas 75221		8. Farm or Lease Name State "B" 2330
4. Location of Well UNIT LETTER C, 560 FEET FROM THE North LINE AND 1977.7 FEET FROM THE West LINE, SECTION 31 TOWNSHIP 16-S RANGE 36 E NMPM.		9. Well No. 1 SWD
15. Elevation (Show whether DF, RT, GR, etc.) 3932 GR, 3952.3 KB		10. Field and Pool, or Wildcat Shoebarn East Devonian
12. County Lea		

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been replaced by State "L" 736 "SWD" and is no longer needed. Plan to start operations approximately 9-27-74.

- Set cast iron bridge plug in 5 1/2" casing at 10,280' and dump 35' of cement on top of bridge plug.
- Set cast iron bridge plug in 5 1/2" casing at 5850' and dump 35' of cement on top of bridge plug.
- Shoot off 5 1/2" casing at approximately 4400'.
- Set 75 sack cement plug at 5 1/2" stub up to 50' above base of intermediate string.
- Shoot off 9 5/8" casing at approximately 2100'.
- Set 70 sack cement plug above 9 5/8" stub.
- Set 70 sack cement plug at 384' to 284' in and out of 12 3/4" surface casing.
- Set 10 sack plug in top of 12 3/4" surface casing.
- Install marker in top of 12 3/4" surface casing.
- Clean and level location.
- You will be notified when location is ready for inspection.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joe D. Ramey TITLE Prod. Supt. DATE 9/16/74

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE SEP 18 1974

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 17 1964  
OIL CONSERVATION COMM.  
HOUSTON, TEX.