

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NOV 15 1970

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E 1328

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry Hole</u>	7. Unit Agreement Name
2. Name of Operator <u>Pennzoil United, Inc.</u>	8. Farm or Lease Name <u>Skelly State</u>
3. Address of Operator <u>P. O. Drawer 1828 - Midland, Texas 79701</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>U</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>5</u> TOWNSHIP <u>16-S</u> RANGE <u>34-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Wildcat</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4147.5 GL</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set plugs as follows:

Plug #1 25 sx @ 11,135'  
Plug #2 25 sx @ 10,659'  
Plug #3 25 sx @ 9,520'  
Plug #4 25 sx @ 7,823'  
Plug #5 25 sx @ 5,980'  
Plug #6 25 sx @ 4,470'  
Plug #7 50 sx @ 1,450'  
Plug #8 10 sx @ Top of surface

Completed P&A 9:30 A.M. 3-10-70

Dry hole marker placed.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Drilling Superintendent</u>	DATE <u>3-11-70</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>Geologist</u>	DATE <u>000 11 1970</u>
CONDITION OF APPROVAL, IF ANY:		